
		Structures maintenance/ renewal funding request form								
Network area South Canterbury		Structure name Ashburton (Hakaterere) River Bridge			Highway 1S	RP 430/0 6	BSN 4306			
Priority High (year 1)	Work category 215B Structural Bridge Component Replacements		Year constructed: 1931	Map ref. (easting): 1498819	Map ref. (northing): 5137422					
Proposed Works Inject cracks in beam ends. Jack all beams at every second sliding pier (i.e. every fourth pier) and install an elastomeric bearing pad to reinstate 'sliding'/movement ability. Undertake conventional joint repairs with a sealant.			One Network Road Classification (ONRC): Secondary Collector	Vehicles per day: 23,904	Owner: NZTA	RCA: NZTA				
Structure description 342m long, 32 span, two lane reinforced concrete T-beam bridge founded on reinforced concrete wall piers and driven RC piles. Simply supported detailing with 'sliding' joint over every second pier (although high friction interface may be resulting in some beams no longer 'sliding'). Timber decked and steel joist clip-on footway on the upstream side.			Problem description Failure and leaking of the expansion joints and breakup of the surfacing within the joints. This is starting to cause driver discomfort and the water leakage is exacerbating the cracking in the beams ends (caused by thermal movement). Freeze-thaw effects presents the risk of further damage to the ends of the beams.							
Option assessment			Risk assessment (see Risk Rating worksheet for details)							
Option	Brief details of option considered	Recomm. Option?	Life	Effectiveness	Risk category	Consequence	Likelihood	Risk level		
Do nothing:	Continue to monitor the bridge allow the joints to leak.	No	0-5 yrs	Not effective	Stakeholders	Severe	Possible	High		
Do minimum:	Repair leaking deck joints (PMB) and monitor cracks in beam ends.	No	5-10 yrs	Not effective	Stakeholders	Severe	Possible	High		
Option 1:	Repair leaking deck joints and inject cracks in beam ends.	No	5-10 yrs	Not effective	Stakeholders	Severe	Unlikely	Medium		
Option 2:	Inject cracks in beam ends. Jack all beams at every second sliding pier (i.e. every fourth pier) and install an elastomeric bearing pad to reinstate 'sliding'/movement ability. Undertake conventional joint repairs with a sealant.	Yes	10-20 yrs	Effective	Stakeholders	Severe	Rare	Low		
Option 3:	Inject cracks in beam ends. Jack all beams at every sliding pier (i.e. every second pier) and install an elastomeric bearing pad to reinstate 'sliding'/movement ability. Undertake conventional joint repairs with a sealant.	No	10-20 yrs	Effective	Stakeholders	Severe	Rare	Low		
Recommended option	Option 2: Inject cracks in beam ends. Jack all beams at every second sliding pier (i.e. every fourth pier) and install an elastomeric bearing pad to reinstate 'sliding'/movement ability. Undertake conventional joint repairs with a sealant.									
Reason for recommendation:	Joints are in poor condition and will continue to break up and deteriorate, resulting in driver discomfort. Leakage is also exacerbating the cracking and spalling of the beam ends. Repairing the cracks in the beam ends alone does not address the cause of the cracking and it is expected that the repaired cracks will reopen due to thermal movement. Installing an upgraded bearing at every second sliding pier is recommended initially. The elastomeric pads would be designed to cater for the thermal movement of four spans. The beam ends at the untreated sliding piers would continue to be monitored. If these beam ends start to deteriorate, the beams at these untreated piers can be jacked and bearings upgraded in the future as required.									
Proposed works and methodology			Prioritisation (see Prioritisation Tables worksheet for details)			Justification				
Crack seal the joints with PMB (low cost). Jack all beams at every second sliding pier (i.e. every fourth pier) and install an elastomeric bearing pad to reinstate 'sliding'/movement ability. Undertake conventional joint repairs with a sealant.			Category	Safety	Level of service	Cost deferral	Legal/ environment	If the joints continue to deteriorate, there will be a higher cost for repairs and increased driver discomfort. Safety and capacity of the bridge could also be compromised if the end of the beams spill off and their seating is reduced. In the worst case, this could cause a beam to settle, which has occurred on other similar bridges in the past.		
			Priority	Medium (years 2-4)	High (year 1)	High (year 1)	Low (year 5+)			
Consequences of not doing work If repairs are not undertaken, beam end failure similar to observed on the SH67 Orowaiti River Bridge is possible. This could result in the ends of the beams spalling off and possibly failure and settlement of the beams due to their limited seating. Joint leakage is exacerbating this, and is also starting to lead to breaking up of the asphalt and driver discomfort.										
Document preparation										
Prepared by s 9(2)(a)			Title Service Line Leader Bridge Asset Manager			Date 1/10/2019				
Approved by s 9(2)			Title Senior Bridge Engineer			Date 3/10/2019				
Summary										
Highway	BSN	Asset name	Network area	Work category	Proposed works	Cost	Life	Effectiveness	Priority	Prioritisation category
1S	4306	Ashburton (Hakaterere) River Bridge	South Canterbury	215B	Inject cracks in beam ends. Jack all beams at every second sliding pier (i.e. every fourth pier) and install an elastomeric bearing pad to reinstate 'sliding'/movement ability. Undertake conventional joint repairs with a sealant.	\$ 550,000	10-20 yrs	Effective	High (year 1)	Level of service
Document review - RAPT response										
Reviewed by s 9(2)(a)			Title Principal Structures Engineer			Date 24/02/2020				
Outcome		Comments								

Network area: South Canterbury	Structure name: Ashburton (Hakaterere) River Bridge	Highway: 1S	RP: 430/0.6	BSN: 4306
Work category: 215B Structural Bridge Component Replacements	Year constructed: 1931	Map ref. (easting): 1498819		
	One Network Road Classification (ONRC): Secondary Collector	Map ref. (northing): 5137422		
Proposed Works: Inject cracks in beam ends. Jack all beams at eve	Vehicles per day: 23,904	Owner: NZTA		
	% heavy vehicles: 8.7%	RCA: NZTA		

Photos/plans



Figure 1 - Typical deterioration of deck joints



Figure 2 - Typical deterioration of deck joints, showing breakup and leakage.

Released under the Official Information Act 1982

Network area: South Canterbury	Structure name: Ashburton (Hakatere) River Bridge		Highway: 1S	RP: 430/0.6	BSN: 4306
Work category: 215B Structural Bridge Component Replacements	Year constructed:	1931	Map ref. (easting):	1498819	
	One Network Road Classification (ONRC):	Secondary Collector	Map ref. (northing):	5137422	
Proposed Works: Inject cracks in beam ends. Jack all beams at eve	Vehicles per day:	23,904	Owner:	NZTA	
	% heavy vehicles:	8.7%	RCA:	NZTA	

Photos/plans



Figure 3 - Cracking at beams ends like due to thermal movement (lack of appropriate sliding surface) and exacerbated by water leakage



Figure 4 - Cracking at beams ends like due to thermal movement and exacerbated by water leakage. Could lead to spalling and seating

Released under the Official Information Act 1982

Network area: South Canterbury	Structure name: Ashburton (Hakatere) River Bridge		Highway: 1S	RP: 430/0.6	BSN: 4306
Work category: 215B Structural Bridge Component Replacements	Year constructed:	1931	Map ref. (easting):	1498819	
	One Network Road Classification (ONRC):	Secondary Collector	Map ref. (northing):	5137422	
Proposed Works: Inject cracks in beam ends. Jack all beams at eve	Vehicles per day:	23,904	Owner:	NZTA	
	% heavy vehicles:	8.7%	RCA:	NZTA	

Photos/plans



Figure 5 - Typical corrosion of footway joints. Will require recoating in a few years (at risk of section loss in a few areas).

Figure 6 -

Released under the Official Information Act 1982