ŌTAKI TO NORTH OF LEVIN PFRs Report No. 3: Manakau to Ohau Bridges

Prepared for NZ Transport Agency February 2013



This document has been prepared for the benefit of NZ Transport Agency. No liability is accepted by this company or any employee or sub-consultant of this company with respect to its use by any other person.

This disclaimer shall apply notwithstanding that the report may be made available to other persons for an application for permission or approval to fulfil a legal requirement.

QUALITY STATEMENT

PROJECT MANAGER	PROJECT TECHNICAL LEAD	
Tracy Couchman	Phil Peet	
PREPARED BY		
lan Robertson		
CHECKED BY		
Phil Peet		
REVIEWED BY		
Marten Oppenhuis		
APPROVED FOR ISSUE BY		
Phil Peet	//	
WELLINGTON		

Level 1, 123 Taranaki Street, Wellington 6011 PO Box 9624, Te Aro, Wellington 6141 TEL +64 4 381 6700, FAX +64 4 381 6739

REVISION SCHEDULE

Rev Date No		Description	Signature or Typed Name (documentation on file).			
No	Date	Description	Prepared by	Checked by	Reviewed by	Approved by
А		Draft	JP	PP	МО	PP





Executive Summary

This Project Feasibility Report (PFR) is one of a number of reports being undertaken to determine the package of improvements that should be implemented in the short to medium term to improve the safety and efficiency of the highway between Ōtaki and north of Levin as part of the Wellington Northern Corridor Road of National Significance (RoNS).

The purpose of this report is to determine the feasibility of improving the section of State Highway 1 (SH1) between Ohau and Manakau townships. Presently, this 4.95 km section of road exhibits a number of concerning features including poor geometry (with substandard vertical and horizontal curvature), five substandard bridge structures approaching the end of their design life, significant crash history as well as a number of historically and culturally significant landmarks.

A variety of options are considered, with two taken forward to more detailed assessment. A cost estimate is provided for each of these together with an economic assessment and resultant Benefit-Cost Ratio.

Option 3-1 considered upgrading the existing alignment, with improved curvature and enhanced cross section and passing lane opportunities. To ensure high standard curves and to avoid key locations of significance, a large proportion of this option requires greenfield construction. This option would require four new bridge or main culvert structures.

Option 3-2 is based upon bypassing the existing alignment between Waikawa Stream and Ohau River and running parallel to the rail alignment. This option is almost entirely greenfield construction. Option 3-2 would not require any rail overbridges as the alignment stays on the west side of the rail throughout the project extents, but would require three bridge or culvert structures.

A summary of the economic analysis is shown below.

Option Description	Capital Costs	NPV Benefits	Benefit Cost Ratio
Option 3-1: Upgrade Existing	\$50.3M	\$18.0M	0.4
Option 3-2: Rail Alignment	\$36.4M	\$39.1M	1.1

Table 1-1: Option Summary

The BCR for Option 3-2 is clearly the higher of the two options, primarily because the route length and construction costs are lower than Option 3-1, with the route being more direct and avoiding the requirement for two rail overbridges. Whilst Option 3-2 is the best solution in this instance, it is nonetheless recommended that both options be considered further as part of the overall short, medium and long terms strategy for Ōtaki to Levin. Given this PFR is just one of a number being considered, it is recommended that both options be considered with due cognisance of the other adjacent PFRs (and associated improvements) to ensure compatibility.





NZ Transport Agency

Report 3: Manakau to Ohau Bridges

CONTENTS

ii
1
1
3
3
3
3
7
7
7
0
0
0
1
2
4
5
6
7
7
7
8
8
8
9
9
0
0
1
1
1
2
2
2
3



15 Resource Management Issues	23
15.1 District Plan Provisions	23
15.2 Regional Plans	23
15.3 Other Provisions	24
16 Maintenance Issues	24
17 Conclusions and Recommendations	24

LIST OF TABLES

Table 1-1:	Option Summary	ii
Table 5-1:	Saturn Base 2011/2041 Network Modelling Results	7
Table 6-1:	Annual Distribution of Crashes	8
Table 6-2:	CAS Crash Type	8
Table 6-3:	HRRRG Crash Type	8
Table 6-4:	Crash Causation Factors of Reported Injury Crashes	9
Table 6-5:	Environmental Factors	9
Table 9-1:	Cost Estimates	.16
Table 10-1	Travel Time Benefits	.18
Table 10-2	Vehicle Operating Cost Benefits	.18
Table 10-3	Passing Lane Benefits	.18
Table 10-4	Crash Benefits	.18
Table 10-5	Economic Analysis Summary	.19

LIST OF FIGURES

Figure 2-1: Projects Currently Being Investigated	2
Figure 4-1: Study Area Location Plan	4
Figure 4-2: Key Historic & Cultural Landmarks	6
Figure 7-1: Typical Passing Lane Cross Section	14
Figure 7-2: Typical Bridge Cross Section	15
Figure 7-3: Typical Cross Section	15

APPENDICES

- Appendix A Photographs
- Appendix B Traffic Data
- Appendix C Crash Data
- Appendix D Outline Plans
- Appendix E Cost Estimates
- Appendix F Economic Analysis Worksheets
- Appendix G Bridge Condition Data



1 Introduction and Background

Using the outcomes of the Ōtaki to North of Levin Scoping Report and addendum, the NZTA decided that the most appropriate strategy for the highway between Ōtaki and north of Levin is to upgrade the existing highways as the first stage of a long term strategy. This allows the NZTA to realise important safety benefits in the short to medium term whilst deferring the need to construct four lanes for the time being.

This Project Feasibility Report (PFR) is one of a number of reports being undertaken to determine the package of improvements that should be implemented to improve the safety and efficiency of the highway between Ōtaki and north of Levin as part of the Wellington Northern Corridor Road of National Significance (RoNS).

The objectives of the Wellington Northern Corridor RoNS, which runs from Wellington Airport to north of Levin, are:

- To enhance inter regional and national economic growth and productivity;
- To improve access to Wellington's CBD, key industrial and employment centres, port, airport and hospital;
- To provide relief from severe congestion on the state highway and local road networks;
- To improve the journey time reliability of travel on the section of SH1 between Levin and the Wellington Airport; and
- To improve the safety of travel on state highways.

For the Ōtaki to north of Levin section; the objectives are:

- To provide best value solutions which will progressively meet (via a staged approach) the long term RoNS goals for this corridor of achieving a high quality four lane route;
- To provide better Levels of Service, particularly for journey time and safety, between north of Ōtaki and north of Levin;
- To remove or improve at-grade intersections between north of Ōtaki and north of Levin;
- To engage effectively with key stakeholders; and
- To lodge Notices of Requirement and resource consents as appropriate with the relevant consent authorities for the first individual project by the 2013/14 financial year.

The projects that are being developed to help meet these objectives are presented in Section 2.

The purpose of this report is to determine the feasibility of undertaking improvements to aid road safety and traffic flow between the Manakau and Ohau townships on State Highway 1 south of Levin.

The geographical extent of this project commences just south of the Manakau Rail Overbridge to immediately north of the Ohau River Bridge. The study area therefore includes 5 bridge structures, namely; Manakau Rail Overbridge, Waikawa Stream Bridge, Kuku Stream Bridge, Ohau Rail Overbridge and Ohau River Bridge. It is noted that SH1/57 & Arapaepae Curve (PFR No. 5) Manakau Settlement (PFR. No. 2) and the Ohau Settlement (PFR No. 4) either adjoin or have sections included within the geographical length of this PFR.

The outcome of this PFR will be considered alongside the outcomes of the other PFRs and used to determine the best package of works to progress as the first stage of the long term strategy.

2 Projects Currently Being Investigated

The projects that are currently being investigated to meet the short to medium term objectives of the Otaki to north of Levin RoNS project are presented in Figure 2-1:






Figure 2-1: Projects Currently Being Investigated

In addition to the above PFRs, reports are also being undertaken on Route Improvements (i.e. edge treatments, passing lanes, walking and cycling, side friction etc; Report No. 11) and on Four Lane Alignments (Report No. 12).



3 Description of Problem

3.1 Ōtaki to North of Levin

State Highway 1 and State Highway 57 through the study area have a number of deficiencies, resulting in a poor crash history and a number of locations where the free flow of vehicles is restricted by the tight physical characteristics of the highway.

State Highway 1 currently follows the historic route established in the late 19th and early 20th centuries. As a consequence it is constrained by a now substandard alignment, towns and settlements, narrow curved bridges and significant side friction caused by local roads, commercial frontages and property accesses for the entire stretch.

3.2 Manakau to Ohau Bridges

The section of road under consideration in this PFR is approximately 4.95 km in length running from RP985/3.00 to RP985/7.87, or 1.0 km south of the central point of the Manakau Railway Overbridge to the immediate north side of the Ohau River bridge.

Throughout this length of highway there are a number of key issues that are required to be addressed by the improvement works. The majority of the concerns along this section of the highway relate to substandard road geometry, although other concerns exist due to adjacent land uses. These key factors and constraints considered in this PFR are:

- Five substandard bridges all with 20-35 years remaining life
- Width of bridges
- A number of substandard horizontal curves including broken back over Manakau Rail and Waikawa River all substandard (down to 200 m radius and including advisory speed reduction)
- Deficient vertical curvature, often in combination with deficient horizontal curves
- Issues with vehicle speeds, passing lanes, and side roads in the vicinity of the Tukorehe Marae


The safety record for this length of highway is relatively poor with a total of 52 crashes recorded in the five year period 2007 to 2011, with two fatal and three serious injury crashes being recorded.

4 Site Description

The project area consists of a 4.95 km length of SH1 and includes five bridge structures. The terrain throughout this section is primarily flat though there are some localised vertical grade changes caused by bridge construction.

This section of SH1 is a two lane undivided highway with approximately 3.5 m lane widths. There is a lack of uniformity in shoulder width, though long sections do include a shoulder of between 1.5 m - 2.0 m.

Figure 4-1 below shows the study area:








Figure 4-1: Study Area Location Plan

There are 4 side roads within the study area (all no exit):

- Kuku Beach Road (RP985/4.16), serving a small number of residential properties and the coastal area being accessed.
- Kuku East Road (RP985/4.30), which generally serves an area of farming and agriculture
- Whakahoro Road (RP985/7.08), 1.5km in length, narrow access road to a small number of properties.
- North Manakau Road (985/7.51), which provides access to a small number of farming properties.

There are also two passing lanes located within the study area. These are:

• A northbound passing lane on SH1 from RP985/6.09 to RP985/5.45 (length 640m inclusive of tapers)



 A southbound passing lane on SH1 from RP985/3.50 to RP985/4.00 (length 500m inclusive of tapers)

The road is also a Limited Access Road (LAR).

The North Island Main Trunk (NIMT) rail line runs predominantly parallel to SH1 for a large section of the Otaki to Levin study area. However, for almost the entirety of this PFR study area the existing SH1 road alignment deviates away from the rail alignment. For this to be achieved, two SH1 rail overbridges transition the SH1 from the west of the rail, to its eastern side immediately south of Waikawa Stream, and then back from the east to the west of the rail alignment immediately south of the Ohau River.

The five bridges within the study area, including their assessed condition1 are described below:

- Ohau River Bridge RP985/3.16 (SH1 BSN 9880), built 1953, current condition is reasonable with an expected remaining life of 30+ years.
- Ohau Rail Overbridge RP985/3.29 (SH1 BSN 9883), built 1956, current condition is reasonable with an expected remaining life of 30+ years
- Kuku Stream Bridge RP985/4.953 (SH1 BSN 9894), built 1929, current condition is reasonable with an expected remaining life of 25+ years
- Waikawa Stream Bridge RP985/6.55 (SH1 BSN 9915), built 1929, current condition is reasonable with an expected remaining life of 20 years
- Manakau Rail Overbridge RP985/6.94 (SH1 BSN 9919), built 1938, current condition is fair, expected remaining life 20 years

Apart from Kuku Stream Bridge, all the other structures are either themselves deficient or within areas of deficient geometry. The consequence is the level of service to road users is progressively reducing. It is not clear whether any of these bridges include seismic design features. Additional bridge data is provided in Appendix G.

¹ Information provided by Bloxham Burnett Olliver to MWH August 2012 via email.








Figure 4-2: Key Historic & Cultural Landmarks

Some of the major constraints within the project area include:

- Kuku Dairy Factory Historic Building,
- Wehi Wehi Marae south of Manakau Rail Bridge,
- Tukorehe Marae, just north of Kuku,
- Tatum Park,
- St. Stevens Church,



5 Traffic Statistics

The Annual Average Daily Traffic (AADT) flow at the NZTA telemetry count site at Ohau (Count Site ID: 01N00988) was 14,600 vehicles per day (2011) with the proportion of Heavy Commercial Vehicles (HCVs) at 10%.

The traffic growth rate at the count site is calculated to be 1.3%, using data from 1992 to 2011. Volumes typically increased from 1992 to 2005; however since then volumes have remained generally stable (the last 3 years have all remained approximately stable.

Limited count data exists for Kuku Beach Road and Kuku East Road. A count was undertaken at Kuku Beach Road in 2011 which revealed AM peak period (7am-9am) two way traffic flow as being 125 vehicles, and the two hour PM (4pm-6pm) peak period counting 132 vehicles two-way. Both Kuku East Road and Kuku Beach Road were included in the Saturn Modelling analysis of the base network:

Year	Link LoS	Kuku East Road Intersection LoS	Kuku Beach Road Intersection LoS
2011 AM	В	С	В
2011 IP	В	В	В
2011 PM	В	С	С
2041 AM	В	F	В
2041 IP	В	С	С
2041 PM	В	F	E

 Table 5-1:
 Saturn Base 2011/2041 Network Modelling Results

Further traffic information is provided in Appendix B.

6 Crash History

6.1 Crash Data

A review of NZTA's CAS database over the five-year period from January 2007 to December 2011 revealed a total of 52 crashes within the study area, which comprises the section of SH1 from 1.0 km south of the Manakau Rail Overbridge in the south (RP985/7.95), to immediately north of the Ohau River Bridge in the north (RP985/3.02), a section length of approximately 4.95 km.

The project area has been assessed using the High Risk Rural Roads Guide² (HRRRG), to determine personal and collective risk.

The following tables provide a summary of the CAS output data for the study area:

² High Risk Rural Roads Guide (HRRRG), NZTA, September 2011



Table 6-1: Annual Distribution of Crashes

Year	Fatal	Serious	Minor	Non-Injury	Total	DSi*
2007	1	-	2	4	7	2
2008	1	-	2	7	10	1
2009	-	1	2	9	12	1
2010	-	2	3	9	14	2
2011	-	-	4	5	9	0
Total	2	3	13	34	52	6

* Death and serious injury casualties

Table 6-2: CAS Crash Type

Crash Type	Number of Reported Crashes	Percentage of Reported Crashes
Overtaking	4	8%
Straight Lost Control / Head on	8	15%
Bend Lost Control / Head on	17	33%
Rear End / Obstruction	17	33%
Crossing / Turning	4	8%
Pedestrian Crashes	-	0%
Miscellaneous Crashes	2	4%
Total	52	100%

Table 6-3: HRRRG³ Crash Type

Crash Type	Number of Reported Crashes	DSi	Percentage of Reported Crashes
Head-on	3	3	4%
Run-off Road	23	3	44%
Intersection Crashes	2	_	4%
Other	24	-	46%
Total	52	6	100%

The crashes classified as 'Other' above include eight crashes resulting in a rear end collision from queued traffic, together with a further four collisions with non-vehicular obstructions.

³ High Risk Rural Roads Guide (HRRRG), NZTA, September 2011



Causation	Number of Reported Injury Crash Causation Factors
Alcohol	4
Too fast	6
Failed giveway/stop	1
Overtaking	3
Incorrect lane/position	14
Poor handling	13
Poor observation	18
Poor judgement	9
Fatigue	3
Vehicle factors	4
Road factors	8
Weather	3
Other	9

Table 6-4: Crash Causation Factors of Reported Injury Crashes

Table 6-5: Environmental Factors

	Wet	Dry	Night	Day	Weekend (Fri 6:00PM to Monday 5:59AM) Weekday
No.	24	28	18	34	19 33
%	46	54	35	65	37 63

Of the crashes occurring within the 4.95 km length of the study area:

- Two were fatal, three were serious, thirteen were minor and thirty-four were non-injury.
- One fatal crash involved a vehicle losing control on a curve crossing the centreline and colliding with an oncoming truck head-on and resulted in two fatalities. The second fatal crash involved a vehicle heading south, losing control in wet conditions and colliding with a tree. The use of a cell phone was suspected.
- 23 (44%) involved runoff road movements resulting in one fatal and two serious injury crashes (3 DSi), and a further 9 minor injury crashes.
- Only 2 crashes (4%) involved intersection related crashes, resulting in 1 minor injury. Given the lack of intersections along this length this low number is unsurprising.
- Throughout the five year analysis period of the project length, there were only three head-on crashes though these were severe in nature with one fatal and one serious injury crash, resulting in 3 DSi.
- The main crash types were loss of control on a bend together with rear end type collisions which made up 66% of all crashes within the study period.
- 'Poor Observation' was a causal factor in 35% of crashes, with incorrect lane / positioning or poor handling also a contributory factor in 27% and 25% of crashes respectively.
- 32 (62%) crashes involved objects being struck; e.g. bridge, fence, ditch, tree etc.



6.2 Crash Risk

The section of SH1 was analysed according to the High-Risk Rural Roads Guide (HRRRG) which identifies that crash risk can be generally defined in two ways:

- Actual Crash Risk; which is based on crashes reported in the last 5 years. This is separated into collective risk, which is also known as crash density, and personal risk, which is also known as crash rate.
- Predicted Crash Risk; which is based on KiwiRAP road protection score (RPS) and the KiwiRAP star rating.

In terms of crash risk this 4.95 km section of SH1 has:

- A collective risk of 0.20 high-severity (fatal and serious) crashes per km per year;
- A personal risk of 3.78 high-severity crashes per 100 million vehicle km; and
- A KiwiRAP calculated star rating of 2.6 and a published rating of 2 star (for the 4.5 km section RP985/3.00 to RP985/7.50), together with an RPS of 14.2.

The collective risk metric is considered 'High' while the personal risk is 'Low' for this section of highway. As a result of a high collective crash risk, KiwiRAP star rating & RPS and reported fatal and serious injury crashes reported in the 5 year analysis period (5 in total), this section of SH1 is therefore classified as a high risk rural road. This is an expected result given the deficiencies identified

Further Crash Data can be found in Appendix C.

7 Options Considered

Two options, which address the alignment and passing lanes, have been consider for the section of SH1 from North of Waikawa Beach Road to South of Bishops Road with the main aim of improving safety and efficiency. Both options considered include passing lanes and bridge crossings of the Waikawa Stream, Kuku Stream, and Ohau River.

The Do-minimum option is to retain the existing 4.95 km alignment and geometry / alignment and continue with periodic maintenance. Given the age and expected service life of some of the existing five bridge structures, within the 30 year do-minimum analysis period, it is anticipated that three of these structures (Kuku Stream Bridge, Waikawa Stream Bridge and Manakau Rail Overbridge) would require replacement. The cost (and timeframe) of this replacement is therefore included withion the economic analysis.


The two options are outlined below:

Option 3-1 Upgrade Existing – Involves utilising the existing alignment but upgrading to an improved standard by removing the short curve radii, providing improved passing lanes with an enhanced highway cross section.

Option 3-2 New Parallel Railway Alignment – Effectively 'straight-lines' through the curved sections between Manakau and Ohau, following alongside the rail alignment, staying on the western side of the rail throughout. As there is no requirement to cross the rail line, this option avoids the need for any rail structures.

7.1 Options Excluded

A variety of options were considered at the concept stage. These concepts broadly followed the principle of upgrading the existing route or providing a new alignment running parallel to the rail line. There was only one feasible option for a railway alignment and this has subsequently been taken forward to option assessment. Two further main options were considered for improving the existing alignment. These are briefly described below:





7.1.1 Curve South of Waikawa Stream

An 1100 m curve, departing the existing alignment to the east immediately north of Manakau township and then crossing to the east of the rail line north of Waikawa Stream and joining back into the existing alignment at around RP 985/4.70. The alignment would then transition west of the existing once more, before rising over the rail alignment, just south of Ohau River, where a new river crossing would be provided to the immediate east of the existing Ohau River Bridge.

This option was discounted on the basis of being circuitous with other options likely to deliver improved travel time savings for a reduced capital cost.

7.1.2 Bifurcation or Intersection: North East of Existing Kuku Stream Crossing

This option effectively continued the straight section between Waikawa Stream and St Stephens Church to remove the existing curve at RP985/4.70 forming a straight section of highway that could bifurcate with a proposed bridge and link formed to SH57 with a proposed connection and river bridge to the existing SH1 north of Ohau River. An alternative arrangement was also considered incorporating a roundabout or interchange in a similar position to the bifurcation.

This option was initially discounted because of the two river crossings required if a bifurcation or interchange was introduced south of the Ohau River. However, the comments in PFR No.5 relating to this concept option should be noted i.e. this option may still warrant consideration at the SAR stage as despite the earlier additional capital outlay for construction, this may provide a better long term solution for route shortening, shorter length bridges, associated travel time benefits and property impact.

7.2 Option 3-1: Upgrade Existing

See Appendix D for outline plans.

Whilst this option does follow the general path of the existing alignment, given the current curve radii is so low at various sections throughout the study area, it is inevitable that a number of sections will be required to deviate from the existing alignment to ensure curves of 1100 m⁴ (110 km/h design speed) can be provided throughout which future proofs for the 4-laning. Approximately 1400 m of this option would be contained on the existing highway, whilst approximately 3600 m would be greenfield construction (total length of 5.0 km).

In addition, passing lanes have been provided in both a northbound and southbound direction, adjacent to each other within the project length, with the passing lane lengths being approximately 1400-1500 m (a significant lengthening of the current passing lane provision). Initially, providing the passing lanes in a staggered, 2+1 layout was considered. However, the alignment of the route, even with the improved curve radii, is not suited to this arrangement. According to Austroads passing lanes are best located on larger radius curves⁵ as proposed here, in combination with the passing lanes commencing on straight sections. Within the passing lanes a central median and wire rope barrier is proposed as described in Section 7.4.1.

For the passing lane sections, the full 4-lane median divided cross section has been assumed, and for the remainder of the project length the improved two lane cross section is proposed (i.e. two 3.5 m traffic lanes with 2.0m sealed shoulders).

Within the option there are 4 local roads intersecting SH1. The intersection with North Manakau Road should be investigated further at the SAR stage to determine a suitable arrangement to connect to SH1 (as Option 3-1 is proposed to elevate SH1 at this intersection as the road level is rising over the rail). Whakahoro Road will be unaffected by this option.

Kuku East Road and Kuku Beach Road are both located within the passing lanes section where a central median with wire rope barrier is proposed. These roads would therefore become left in / left out

⁴ 1100 m curve radii were adopted as per the NZTA RoNS guidelines and to future proof for any long term four laning. However, it is noted that other RoNS project are being constructed with a curve radii down to 800 m. If the lower curve radius was adopted in this situation, the majority of the alignment would still require greenfields construction.

⁵ Austroads Guide To Road Design Part 3: Geometric Design, section 9.4.1



only. No consideration of turn around places has been provided at this stage – however it is recommended that none should be provided within the extent of the passing lanes for safety.

Parts of the existing SH1 would be realigned and the remaining sections of the old alignment reclassified as local roads and used for local access. The intersections with the proposed upgraded SH1 will need to be considered at the SAR stage. This option would affect the quarry access and therefore the layout of this access would also need to be confirmed at the SAR stage.

This option would necessitate the construction of four⁶ proposed structures as follows:

- A proposed rail structure south of the existing Manakau Rail Overbridge, to bring the highway from the west to the east of the rail alignment. This would be a two lane rail overbridge.
- A new bridge crossing over Waikawa Stream, east of the current river crossing. This would require a two lane bridge and should be located where the bridge span can be minimised at a narrow crossing point (to reduce cost).
- A new culvert for Kuku Stream. Four lanes would be required to cross the Kuku Stream as the passing lanes (both directions) are fully developed at this point. It is anticipated that this river crossing could be undertaken using a reinforced concrete boxed culvert structure (potentially two), due to the narrow span and minor waterway required for this stream. Provided this can be achieved, this would result in a significant cost saving in comparison to providing a full bridge structure(s). However, should culverting the watercourse not be suitable, this would require two separate two lane bridge structures. Providing both bridges now is essential to allow the passing lanes to be constructed and would be compatible with the long term 4-laning solution.
- A proposed bridge crossing Ohau River. This would require a two lane bridge and would cross to the east of the existing river crossing. This realigned section of highway would then be required to connect into the appropriate options detailed in PFR No. 5.

It should be noted that a more detailed assessment is critical to determine the optimum placement of all bridge structures to ensure that unnecessary construction costs are avoided. For example, the proposed Ohau River Bridge proposed in this Option may be better located to achieve a shorter bridge span to minimise capital expenditure. Positions presently depicted are indicative and should be revised accordingly during the SAR stage, with more specialised and detailed assessment and topographical information.

An additional culvert would also be required as the realigned road spans an additional (minor) watercourse south of Kuku Stream.

An alternative alignment has been shown indicatively on the plans (Drawing No. 80500902-03-001-001). This alternative utilises more of the existing road corridor and therefore could be preferable as this will avoid greater land acquisition costs and property severance. However, this alternative option would require the relocation of the historic St. Stevens Church which could prove problematic or prohibitively costly, but should at least be considered in the SAR.

No turnaround facilities have been considered at this stage (which are likely to be required given the central median and wire rope barrier).

7.3 Option 3-2: New Parallel Railway Alignment

The lack of rail structures, together with the directness of route (4.7 km total), are the key benefits of this option, but also noting this option is almost entirely greenfield. Another benefit of this option is the new state highway would avoid listed or cultural buildings of significance (though some disruption for access to these locations would eventuate) which tend to be located along the existing SH1 alignment and therefore constrain the improvements and route alignment when following in close proximity to the existing corridor.

⁶ It should be noted that this PFR (No. 3) ceases at the northern side of the Ohau River. This avoids double counting with the options contained within PFR No. 5, where all of the options considered commence from immediately north of Ohau River. Accordingly this option does not include an additional rail overbridge to transition the alignment to the west side of the rail as some options only require this as part of the SH57 intersection. Therefore these are discussed in PFR. No. 5.



Passing lanes are also provided in both the northbound and southbound directions parallel to each other resulting in a long section of 4-laning (of approximately 1500 m) which is compatible with the long-term 4-laning obejctive. Wire rope central median barrier is proposed for the full length of the passing lanes (and in advance of their commencement) for the reasons described in Section 7.4.1. It has been possible to propose the passing lane length (approximately 1500 m total for both directions) away from any existing accessways (and maintain control via the Limited Access Road status) which is desirable from a safety and efficiency perspective.

The non-passing lane sections are proposed to include two 3.5 m traffic lanes and two 2.0 m sealed shoulders, swale drainage (of around 4.0 m width) and no central median or wire rope barrier.

For the side roads within this section, North Manakau Road and Whakahoro Road intersections with SH1 would need to be considered at the SAR stage but are likely to remain as T intersections with SH1.

Kuku Beach Road would be bisected by the realigned SH1 and central median wire rope barrier would prevent right turns in or out of both the east and west section of Kuku Beach Road. The detail of the intersections should be considered at the SAR stage but one option may be left in and left out only for Kuku Beach Road West, and all access to Kuku Beach Road East taken from the old SH1 which would be declassified to local road status. Provision of U turn facilities would provide for local turning facilities.

With the declassification of the old SH1 to local road, Kuku East Road would no longer form an intersection with the new SH1 alignment and access would remain as is currently the case.

The quarry access would remain unaffected by this alignment and could still be accessed from the declassified SH1. The form and use of the intersections with the existing (declassified) SH1 should be considered in the SAR.

Option 3-2 will necessitate the provision of a number of proposed bridges as described below:

- A proposed two lane bridge would be required at Waikawa Stream, west of the existing bridge. The stream is particularly narrow at this point and so there could be an opportunity to instead provide a box culvert to secure construction costs savings (though a full bridge structure has been included in the cost estimate).
- A proposed culvert over Kuku Stream. Four lanes would be required to cross the Kuku Stream as the passing lanes (both directions) are fully developed at this point. It is anticipated that this river crossing could be performed with a reinforced concrete boxed culvert structure (potentially two), due to the narrow span and minor waterway required for this stream. Provided this can be achieved, this would result in significant cost savings in comparison to providing a full bridge structure(s). However, should a culvert not be suitable, this would require two separate two lane bridge structures. Providing both bridge or culvert structures as part of this project is essential to allow the passing lanes to be constructed and would support the long term 4-laning solution.
- A proposed river crossing of Ohau River west of the existing river crossing. This new crossing would require a single two lane bridge structure, which would then tie-into a new section of realigned SH1 that would connect to the preferred option considered in PFR No. 5.

An additional culvert will be required as the realigned road spans an additional (minor) watercourse south of Kuku Stream.

An alternative alignment has been shown indicatively on drawing number (Drawing No. 80500902-03-001-002) which incorporates a curve of 1100 m at the southern end of the study area in the vicinity of the Waikawa Stream Bridge. There may be benefits in pursuing this alternative alignment should the interface with (and disruption to) the existing properties fronting SH1 at this location prove problematic.

A line item has been included in the cost estimation for the relocation of services – however, given this option proposes to significantly alter the SH1 alignment, it is entirely feasible that further service relocations could be necessary. The proposed alignment does not preclude location of future services, but overhead facilities with poles should be avoided.

No consideration has yet been given to retaining the existing rail overbridges for access to the current SH1 through Kuku. This will need further investigation during the SAR in conjunction with maintenance, safety and constructability requirements.



7.4 Typical Cross Section

Three different cross sections are used throughout the study area, as described below.

It is also important to recognise that clearzones have not been incorporated into this PFR – the corridor widths shown are purely to give some flexibility within the designation. Batter slopes could potentially be steepened to reduce earthworks and land requirement. Moreover, where the risk of runoff road crashes is high, edge protection (principally using wire rope barrier) is the preferred option (from both a safety and economic perspective). However, edge protection on the relatively flat terrain is not shown or proposed for this PFR. Whilst there are a significant number of runoff road crashes within the project area, the improvements to the vertical and horizontal geometry will result in significant safety improvements (i.e. reducing the likelihood of runoff road events happening in the first instance – thereby treating the cause rather than the effect). Should it be deemed that edge protection is still required at critical locations, then it may be introduced - however it is not proposed as a corridor-wide treatment at this stage.

7.4.1 Typical Section at Passing Lanes

The passing lanes for both northbound and southbound traffic are provided adjacent to each other in both options. As such, it has been deemed appropriate to provide the full 4-laning solution cross section to avoid abortive works and redundancy at a later stage. This is also justified on the basis that with the provision of four lanes, shoulder and median in the short term, upgrading to the four lane solution at this stage will incur relatively modest cost increases, delivering greater value for money (by undertaking the full 4-laning work at this stage). Given the more aggressive behaviour of drivers at passing opportunities, wire rope barrier is proposed in the central median throughout the full length of the project where passing lanes are provided. Therefore the typical cross section for the passing lane section consists of:

• A 3.0 m median with wire rope barrier

With the following for both directions of travel:

- A 1.0 m sealed median shoulder
- Two 3.5 m traffic lanes
- A 2.5 m sealed shoulder
- A 0.5 m unsealed shoulder
- Edge protection in the form of guardrail or wire rope barrier
- A feathered edge and swale drain (of width to be determined dependant on topography, pavement depth and cut / fill requirements)

The above highway cross section has been assessed to require a nominal cross section width of approximately 50 m.




Figure 7-1: Typical Passing Lane Cross Section

7.4.2 Typical Section on Bridges

The typical cross section for the bridges comprises an undivided two lane arrangement with shoulders (two 3.5 m lanes with two 2.5 m sealed shoulders and New Jersey Type solid concrete TL5/6 edge



barrier). Where a bridge is required within the passing lane sections, then the 2 lane bridge would be replicated side by side.




Figure 7-2: Typical Bridge Cross Section

7.4.3 Typical Section on Non-Passing Lane or Bridge Lengths

For the sections of the highway between the passing lane sections and bridge structures, an upgrade (widening) to the existing road alignment is proposed (with new greenfields lengths having a corresponding cross section). The typical cross section for these lengths would consist of:

- Two 3.5 m traffic lanes (undivided)
- Two 2.0 m sealed shoulders
- Edge protection in the form of guardrail or wire rope barrier
- Two swale drains (of nominally 4.0m width dependent on topography pavement depth and cut and fill requirements)




Figure 7-3: Typical Cross Section


The above cross section has been assessed to require a nominal cross section of 20 m - 25 m. The provision of a central median and wire rope barrier is not considered essential on these sections as the crash history reveals a limited number of head-on or cross centreline crashes through this section of SH1 where the deficiencies have been a contributing factor (acknowledging that one single head-on collision was responsible for two fatalities on a deficient section). The improved geometry to 1100 m radius on all curves should further improve drivers' ability to negotiate the road curvature and reduce loss of control crashes. Whilst cross centreline crashes were problematic on the Forest Lakes PFR section (PFR No. 1), it is not anticipated that crash migration would take place given the Forest Lakes crashes seem to be a result of poor geometry on that localised section.

8 Design Statement

This project is at a feasibility stage, and therefore several assumptions have been made in the design.

The design assumptions include the following:

• The cost estimate has been based on the judgement of an engineer who has knowledge of the site.





- The cost estimate has been based on the assumption that the project can be built using proven technology.
- TL4 wire rope median barrier is proposed in the central median on the approaches to and through the passing lanes section.
- No scheme-wide edge protection or clearzones are proposed at this stage. The provision of safety barrier has been allowed in the vicinity of embankments and bridge structures. This will need further consideration during the scheme design.
- No adverse ground conditions are encountered (e.g. soft subgrade or contaminated material). Geotechnical testing will be a requirement at the next stage.
- For the structures element, an initial assessment has been undertaken. A full structural assessment should be undertaken at scheme stage, particularly given the lack of topographical and geotechnical information.
- A vertical crest K value of 150 has been utilised to meet safe stopping sight distance requirements for 110 km/h design speed (2.5 s reaction time). A vertical sag curve K value of 80 has been used.
- It is noted that lower vertical curve K values have been recently permitted by NZTA in constrained situations, an example being Christchurch Southern Motorway Phase 1, where it is understood a crest curve K value of 72 was accepted. The use of a relaxed K value has not been considered in detail as part of this PFR but should be considered in future to reduce the extents of bridging structures and approaches.
- Where the existing highway is retained, regrading the carriageway would not generally be required but new surfacing would be laid across the entire width and length of the project.
- Some drainage provision has been included (culverts & headwalls) within the cost estimation but this is estimated based purely on the judgement of a drainage engineer.
- Earthwork batter slopes are assumed to be 6H:1V for fills and 3H:1V for cuts (where these are less than 1 m). On protected embankments, fills 2H:1V have been assumed. Earthwork extents have been estimated as no topographical survey data is available.
- A standard pavement design of 350 mm subbase, 170 mm M4 type basecourse and two coat chipseal has been assumed throughout this PFR.

9 Cost Estimates

The expected and 95th percentile estimates for the options are detailed in Table 9-1 below.

Table 9-1: Cost Estimates

Option Description	Expected Estimate	95 th Percentile Estimate
Option 3-1 – Improve Existing Route	\$50.3M	\$64.6M
Option 3-2 – Railway Alignment	\$36.4M	\$46.7M

To ensure consistency in comparison, both options include upgrades to the existing alignment from RP985/3.02 to RP985/7.95. Option 3-1 excludes an Ohau rail crossing as it is costed in PFR No. 5.

The cost estimates for the options have been calculated using concept layouts of the options and with no survey data, and are based on the design statement assumptions as listed above. The cost estimates for the options are given in Appendix E.



Property costs have been included in the options cost estimation based upon information provided by NZTA to MWH in 2011⁷. These figures are calculated considering land use and zoning and applying a broad land value rate to the areas required for the improvements.

10 Economic Assessment and Risk Assessment

10.1 Basis of Economic Analysis

Economic analysis was carried out in accordance with NZTA's Economic Evaluation Manual (EEM) using a modified version of the simplified procedures.

The following assumptions have been made in the calculation of the Benefit Cost Ratio. They are:

- 1. The base year is 2012 and time zero is 2013.
- 2. Time zero AADT along this section of road is projected to be approximately 16,100 vehicles per day (2013) and annual traffic growth is estimated as 1.2 %.
- 3. The crash analysis has been done for the five calendar year period January 2007 December 2011 and considers the following:
 - a. Do-minimum: Accident by accident Analysis based on Method A of the EEM has been used as there is one or more fatal or serious injury crashes per kilometre.
 - b. Option 3-1 and Option 3-2: Crash Rate Analysis Method B of the EEM has been used as both options are a fundamental change to the site.
 - i. It has been assumed that the speed will increase from 90 km/h for the dominimum to 100 km/h for Option 3-1 and Option 3-2 (as result of the changes to the geometry and alignment)
 - ii. The average gradient is expected to decrease from 3% for the do-minimum to 2% for both options.
 - iii. Since the EEM crash modification factors do not extend beyond a 2.0 m shoulder, we have conservatively assumed that the 2.5 m shoulder benefits are the same as a 2.0 m sealed shoulder for the passing lanes and bridges / structures.
- 4. The 2011 update factors and a discount rate of 8% have been used.

A summary of the economic analysis is detailed in the following sections.

10.2 Travel Time Savings

Improving the road geometry has increased the expected average speed resulting with travel time savings. In addition, Option 2 is shorter than the do-minimum and Option 1.

There may be some disbenefits associated with the additional distance some vehicles will have to travel because of the right turn restrictions associated with the WRB, however these have not been calculated but are likely to be minimal in comparison to the overall travel time savings. Furthermore, they cannot be calculated until the turn around areas have been identified. This extra travel time costs would be similar for both options.

The expected travel time savings are shown in Table 10-1 below.

⁷ Email provided from Mitchell Cocking (NZTA) to Marten Oppenhuis (MWH) on 12 August 2011



Table 10-1: Travel Time Benefits

Option	Travel Time Savings (NPV)
Option 3-1 – Improvements on existing alignment	\$4,970,000
Option 3-2 – New route adjacent railway line	\$17,600,000

The difference in travel time savings between the options is attributed to Option 3-2 being 290 m shorter than Option 3-1.

10.3 Vehicle Operating Cost Savings

There are vehicle operating costs disbenefits for Option 3-1 and savings for Option 3-2 as presented in Table 10-2 below. The disbenefit for Option 3-1 is a consequence of the route length being longer than the do-minimum.

Table 10-2: Vehicle Operating Cost Benefits

Option	VOC and CO ² Savings (NPV)
Option 3-1 – Improvements on existing alignment	- \$2,690,000
Option 3-2 – New route adjacent railway line	\$5,250,000

10.4 Passing Lane Savings

The passing lane saving have been estimated with the NZ Transport Agency Simplified Procedures A7 – Passing Lane analysis tool. The analysis considered the benefits of extending the existing northbound and southbound passing lanes.

The expected passing lane savings are presented in Table 10-3 below.

Table 10-3: Passing Lane Benefits

Option	VOC and CO ² Savings (NPV)
Option 3-1 – Improvements on existing alignment	\$2,800,000
Option 3-2 – New route adjacent railway line	\$2,560,000

Option 3-1 benefits are slightly higher because the passing lanes are 1,725 metres long compared to Option 3-2 being 1,564 metres long.

10.5 Crash Benefits

Widening of the shoulders, significant improvements to the road geometry, extension of the passing lanes and installation of a wire rope median barrier are expected to significantly reduce the severity of fatal and serious crashes which involve vehicles crossing the centreline and running off road.

The expected crash cost savings are shown in Table 10-4 below.

Option	Crash Cost Savings (NPV)	% Saving
Option 3-1 – Improvements on existing alignment	\$12,900,000	48%
Option 3-2 – New route adjacent railway line	\$13,700,000	51%



The difference in crash benefits between the options is solely attributed to Option 3-2 being 290 m shorter than Option 3-1 and therefore the exposure reduced.

The analysis does not specifically account for the installation of WRB, however there will be crash benefits from its installation.

DSi crashes have also been estimated using HRRRG and KiwiRAP methodology⁸.

10.6 Maintenance Costs

Maintenance costs were extracted from RAMM for the previous four years and have been included in the analysis. It has been assumed that the maintenance costs will remain the same for both options, except with the addition of wire rope barrier and additional carriageway width costs.

The additional carriageway costs have been based on \$4.50 /m² for chip seal surfacing.

The average maintenance cost was \$3,000 over the project length per year. There has been a higher maintenance cost in year 2012, where \$27,000 has been spent mainly on stabilisation. This is not considered a typical annual cost.

Barrier maintenance costs have been estimated by using costs associated with the Centennial Highway (Coast Road) Wire Rope Median Barrier and adjusting for the length of barrier. This has been estimated at \$15,000/year for both options. This is conservative as the tight geometric constraints on the coastal section of Centennial Highway would be expected to have a greater number of hits than the section of road covered by this project.

For the do-minimum, the replacement of existing bridges at the end of their design life has been included. The bridges are:

- Waikawa Stream Bridge. To be replaced at year 20 costing \$4,360,000.
- Manakau Rail Overbridge. To be replaced at year 20 costing \$4,820,000.
- Kuku Stream RCBC. To be replaced at year 25 costing \$270,000.

10.7 Benefit Cost Ratio Results

Table 10-5: Economic Analysis Summary

Option Description	Total Cost (NPV)	Total Benefits (NPV)	BCR
Option 3-1 – Improvements on existing alignment	\$48,500,000	\$18,000,000	0.4
Option 3-2 – New route adjacent railway line	\$34,600,000	\$39,100,000	1.1

⁸ Using the HRRRG, a high level assessment has been made of the likely numbers of DSI savings that would result from this project (for either option). Presently, this section of SH1 has a KiwiRAP rating of 2.6 stars. Using the KiwiRAP analysis tool 'What If' Analysis, and introducing all of the improvement measures proposed for Option 3-1 (Option 3-2 is not possible due to the fundamental change in route), then a new calculated Kiwi Star rating of 2.7 is produced. This is not considered realistic for the magnitude of improvements proposed and does not represent the significant crash improvements that would result. Therefore, a reasonable yet conservative assumption with either option is that a new star rating of 3.5 could be achieved, given the alignment improvements, passing opportunities, median and wire rope barrier and improved intersections.

From Appendix C in HRRRG, it is possible to estimate the likely number of fatal and serious crashes on this section. A 3.5 star rating results in a personal crash rate of 11 injury crashes per 100 m Vehicle Kilometres Travelled. Using the HRRRG formula, this results in a projected 4.4 DSi for a 5 year period, as compared with the 6 observed in the five year crash history (a reduction of 1.6 DSi per 5 years).



Option 3-2 has higher total benefits and a lower total cost compared to Option 3-1 therefore has the higher BCR of 1.1.

Incremental BCR analysis shows that Option 3-2 is the preferred option in economic terms.

10.8 Sensitivity Test

The economic analysis and associated BCRs discussed within this section have been calculated using the guidance and processes contained with the EEM. Whilst this is the appropriate method for deriving the BCRs for projects such as this, it is also important to recognise that this methodology can be somewhat misleading, particularly in regard to calculating the likely crash savings resulting from the options. The do-minimum crash costs are calculated on a crash by crash basis, whilst the option costs are calculated using an overall crash rate (given the fundamental change to the site).

Investigation of the crash rate applied (using EEM procedures) suggests an approximate reduction in all crashes of around 50%. However, (using a common sense and investigation principles logic) this is considered to be a very conservative reduction on the basis that both options result in vastly improved alignments (significantly improved vertical and horizontal geometry, improved passing opportunities and bridge structures, improved cross section and wire rope barrier). The existing history includes a number of high severity crashes on the sections of the highway that will be eliminated. Analysis of the 5 year crash data reveals the following:

- 4% Intersection Crashes
- 6% Head-on Crashes
- 44% Run-off Road Crashes
- 46% 'Other' Crashes

The 'Other' category crashes have been assessed and the majority relate to slow vehicles, non-vehicular obstructions and queuing traffic.

Given the existing crash record and the overall magnitude of improvements to the geometry of the highway, it is therefore proposed that a more reasonable crash rate reduction will result. Therefore, a crash reduction of 80% has been applied which is considered a more reasonable outcome of the improvements proposed.

This would result in the following approximate BCR:

- Option 3-1: BCR of 0.5
- Option 3-2: BCR of 1.3

10.9 Risk Assessment

The risks to the project have been assessed using the General Approach as determined in the NZTA Risk Management Process Manual (AC/Man/1).

The major potential risks associated with the Manakau to Ohau Bridges improvement project are considered to be:

- Project unable to get funded due to constrained funding environment.
- Inaccurate cost estimate due to level of available data at this feasibility state, including utility information and assumptions in regards to topography, geotechnical and land value / use.
- Use of reinforced concrete box culvert for Kuku Stream crossing is not feasible and two 2-lane bridge structures are required.
- Conceptual structures type / position are not achievable due to surrounding properties / land uses.
- Incompatibility with adjacent sections improvement works (and preclusion of 4-laning opportunity).
- Traffic delays during construction.



- Environmental effects during construction.
- Impacts on existing services.
- Land acquisition difficulties.
- Difficulties in obtaining resource consents and/or alteration to designation.
- Opposition from local iwi.
- Additional landowner accommodation works required.

11 Assessment Profile

The Government Policy Statement on Land Transport Funding (GPS) requires the NZTA to consider a number of matters when evaluating projects. To assist in understanding how projects perform against these matters and hence what investment decisions to make, the NZTA utilises an assessment profile process.

The assessment profile is a three-part rating for an activity, rated as high, medium or low e.g. HMM, and representing the assessment for Strategic Fit, Effectiveness and Efficiency respectively.

It is considered that the assessment profile⁹ for the Manakau to Ohau Bridges PFR is **HHL**. The following paragraphs outline how this profile has been created.

11.1 Strategic Fit

The strategic fit factor is a measure of how an identified problem, issue or opportunity that is addressed by a proposed activity or combination of activities, aligns with the NZTA's strategic investment direction.

As this project is part of a Road of National Significance and is classified as a High Risk Rural Road, the Strategic Fit is **High**.

11.2 Effectiveness

The effectiveness factor considers the contribution that the proposed solution makes to achieving the potential identified in the strategic fit assessment and to the purpose of the Land Transport Management Act (LTMA).

A wide range of assessment factors are available for use in this effectiveness rating and these draw from the five LTMA areas of:

- Economic Development
- Safety and Personal Security
- Access and Mobility
- Public Health
- Environmental Sustainability

A number of other key criteria need to be considered including integration, consideration of options and responsiveness.

As this project is part of the Roads of National Significance programme, it is recommended that the effectiveness factor for RoNS projects of **High** is adopted.

This is considered appropriate as the project will contribute positively to safety and is consistent with NZTA's strategies and plans.

⁹ NZTA Planning and Investment Knowledge Base, <u>www.pikb.co.nz/assessment-framework</u>



11.3 Efficiency

The economic efficiency assessment considers how well the proposed solution maximises the value of what is produced from the resources used. This is primarily undertaken by the Benefit Cost Ratio.

The options have BCRs of 0.4 and 1.1. Options with a BCR of below 1.0 are considered to have 'no rating' and are considered economically inefficient. Therefore, upgrading the existing alignment (Option 3-1) should be considered in this category, whilst the alignment parallel to the rail line (Option 3-2) has a BCR of between 1.0 and 2.0 which would be considered **Low** efficiency.

In reality, due to the way the PFR projects have been divided, both of these options were always likely to demonstrate a low BCR. This is because for the relatively short length of improved highway within the study area, there are also 5 existing bridge structures that need to be improved or rationalised which somewhat artificially inflates the project costs when considered in short isolated sections.

12 Social and Environmental Assessment

The Scoping Report phase of the Ōtaki to Levin RoNS identified a number of social and environmental factors relating to the Manakau Ohau Bridges PFR which will need to be assessed during the scheme assessment phase. These are outlined below:

- A tangata whenua site of significance (urupa) near to the existing SH1 alignment at Ohau River
- The Ohau River and adjacent river banks as being culturally significant
- Maori owned land adjacent to existing SH1 including the Tukorehe Marae and Wehi Wehi Marae and urupa
- The presence of a historic building south of the Kuku Stream Bridge (Old Kuku Dairy Factory)
- Threated flora in the vicinity of the Ohau River

Consultation has been carried out under the scoping phase of the Otaki to north of Levin RoNS and ongoing consultation will continue with stakeholders throughout the planning and design process. The area is identified as being of cultural importance to the iwi of Rangitane o te Whanganui a Tara, Ngati Raukawa ki te Tonga and Ngati Toa Rangitira.

A Consultation Plan for the project area and consultation will be undertaken in accordance with the plan. The purpose of the plan is to:

- Provide a documented process for intended engagement with the community, including the project context, the parties involved, and desired outcomes;
- Maximise effective and efficient engagement of community within generally tight time constraints;
- Provide the specifics of consultation to be undertaken, including timeframes;
- Help the project team to proactively manage risks to the project/project future from inappropriate or inadequate community engagement; and
- Help the project team to constructively manage community expectations.

13 Geotechnical Requirements

A preliminary geotechnical appraisal report was prepared by MWH in 2011. This report outlined that the majority of the stretch of the highway is underlained by beach deposits (Otaki Sandstone). To investigate the subsurface conditions along the alignment which includes the Manakau to Ohau Bridges study area, MWH recommended field investigations consisting of hand-auger bores, boreholes, test pits and cone penetration tests (CPT).



The preliminary geotechnical appraisal report for the Otaki to Levin RoNS noted the following aspects in regards to the subject study area:

- It has moderate settlement potential;
- It has a seismic potential due to the proximity of the active Northern Ohariu Fault;
- It has moderate susceptibility to liquefaction; and
- It is not located within a tsunami influence zone.

14 Land Requirements

Land requirement has been included in the concept development and cost estimation as follows:

- Option 3-1 requires 175,000m² of land (affecting 70 individual property appellations)
- Option 3-2 requires 180,000m² of land (affecting 23 individual property appellations)

The land calculations are based on that required for the construction of the road using aerial plan areas. It is entirely feasible that these areas will increase when property negotiations take place and entire plots are required to be purchased.

15 Resource Management Issues

The project must meet all statutory requirements. There are a number of documents (both statutory and non-statutory) that must be considered when planning for the state highway improvements. In particular, the requirements of the Resource Management Act, the operative Horowhenua District Plan and the Horizons Regional Plan (proposed One Plan) will be assessed to ensure that the proposed project meets the plan provisions and follows the statutory process.

15.1 District Plan Provisions

15.1.1 Designations

SH1 is designated under the operative Horowhenua District Plan for "state highway purposes" (D2). The existing designation is narrow in places and may need to be altered to accommodate the road improvements in Option 3-1. Option 3-2 will require a realignment of sections of the highway and may require a new designation. Accordingly, it is recommended that the designation boundaries be altered to accommodate these works under s181 RMA. NZTA will be required to give notice to the Council of its requirement to alter the designation (NOR). An outline plan will also be required to indicate the scale of the proposed works within the designation.

Alternatively, NZTA could apply for a resource consent (land use consent) to carry out the proposed works outside the designation.

Sections of SH1 run alongside or traverse the railway line. The railway corridor is designated as D1 under the District Plan.

15.1.2 Heritage Issues

Schedule 2 – Heritage Features of the District Plan identifies the Old Kuku Dairy Factory (H34) (Map 7) in the vicinity of the proposed works.

15.2 Regional Plans

The scheme designs and final construction plans will determine what regional consents are required. The options being investigated involve works that may include work on the bridges over the Ohau River, the Kuku Stream and the Waikawa River.



The following resource consents are likely to be required under the proposed One Plan administered by the Horizon's Regional Council:

- Land use consents for the placement/extension of structures in the riverbed;
- Temporary diversions of water and takes of water during bridge works;
- Bore permit for geotechnical investigation;
- Stormwater discharges from bulk earthworks;
- Soil and vegetation disturbance;
- Gravel extraction;
- Discharges of contaminants to land; and
- Discharge of contaminants to air from road construction.

15.3 Other Provisions

Given that the proposed works may involve earthworks on river/stream banks, there is the potential to unearth Maori artefacts. Current information identifies known sites and an archaeological authority may be required should unknown sites be discovered.

16 Maintenance Issues

The current proposals would result in two specific changes to the maintenance regime:

- Maintenance and repair of new bridge structures for the grade separated solutions noting that the 4 existing structures are all within approximately 30 years of their expected design life.
- Maintenance of additional / new links sections of highway and need to declassify existing State Highway to local road status.
- Option 3-2 would have lower structure maintenance costs with fewer bridge structures.

Both these aspects have been included in the economic evaluations of the options.

17 Conclusions and Recommendations

This report explores the options for improving the section of SH1 between the Manakau and Ohau townships. In addition to the highway having a poor crash history, this route contains a number of problematic or constraining features such as substandard vertical and horizontal geometry, numerous bridge structures and the presence of culturally or historically significant landmarks.

Two options have been explored to improve this section of SH1, the first providing improvements along the general path of the existing alignment, whilst the second option realigns SH1 so that it runs parallel to the rail line through the study area. Both options necessitate a significant proportion of greenfield construction and both provide passing opportunities in both directions.

Benefit-Cost Ratios have been produced for both options and are quoted in the report. It is crucial to reiterate that the BCRs provided should not be considered in isolation as for this particular PFR, they may be misinterpreted as the significant cost of the multitude of bridging structures (compared to the relatively modest crash, VOC and travel time benefits) skews the BCRs negatively. Therefore it is vital that these options (and associated economic outputs) are ultimately viewed in tandem with the other PFR options on adjacent sections. Additionally, the feasibility of each option needs to be considered alongside the preferred options considered in adjacent options to ensure they are compatible (for example ensuring the position of the Ohau River crossing in this PFR, can adequately connect into the preferred Option from PFR No. 5 - SH1/57 Connections).

That said, the BCRs in isolation do give a reasonably good indicator of the absolute costs and benefits of these works in isolation. Option 3-2 is preferred over Option 3-1. This is due to a combination of



factors. Option 3-2 has significantly improved vehicle operating costs than Option 3-1 due to the reduction in project length whilst Option 3-1 necessitates two additional structures and approach earthworks (and is therefore greater capital costs for construction) and Option 3-2 would have lower whole of life costs (which are not considered in 30 year economics) with a reduced number of structures.

Option 3-2 (following the rail alignment) in isolation exhibits a reasonable BCR and therefore would in economic terms be the preferred option. However, it is recommended that both options are considered further as part of the short, medium and long term strategy because of the risks of considering either of these options as a solution in isolation (and ensuring a suitable fit with adjacent PFR No. 5).





Appendix A Photographs





Manakau Rail Bridge Northbound



Manakau Rail Bridge Southbound






Ohau River Structure Northbound



Ohau River Structure Southbound




Appendix B Traffic Data





Appendix C Crash Data




CRASH RO/CRASH DIS CRASH DIRN	INTSN	SIDE ROAD CRASH ID	CRASH DATE CRASH DO' CRAS	HTIMMVMT	TYPE	VEHICLES	CAUSES OBJECT	IS SIROAD CU	IR ROAD W	ETLIGHT	WTHRa	JUNC TYPE TRAF	CTRL ROAD MAFSF	PD LIM FATAL	SERIOUS	MINOR	PERPEFEASTING	NORTHING
1N/985/7.8 300 N		WAIKAWA 2.01E+08	30/11/2010 Tue	755 AC	OTHER	TS1T	372A CFZ	R	D	0	F	N	L	100	0 0		0 1787471	5491296
1N/985/5.! 1450 N		WHAKAHO 2.01E+08	11/12/2010 Sat	1340 AD	RUNOFF	CN1	132A 137A 181A	R	D	В	F	N	С	100	0 0		0 1788710	5493070
1N/985/4.4 200 S		KUKU EAST 2952901	20/06/2009 Sat	1141 AF	OTHER	TN1	129A F	R	D	0	F	Ν	С	100	0 0		0 1789287	5493993
1N/985/6.t 420 N		WHAKAHO 2813001		1920 BC	HEADON	CS1C	121A 404A	М	D	DN	F	Ν	L		0 0			5492300
1N/985/6.9 70 N		WHAKAHO 2710010		1615 BF	HEADON		106A 130A G	М	W	0	L	N	L		2 0			5492078
1N/985/3.9 200 N		KUKU BEA(2.01E+08		1620 BO	HEADON		205A	R	D	В	F	N	С		0 1			5494520
1N/985/4.282	1	KUKU EAST 2950252		1130 CA	RUNOFF		130A 351A F	R	D	В	F	T N	C		0 0			5494193
1N/985/3.9 200 N		KUKU BEA(2.01E+08		2330 CB	RUNOFF		101A F	R	D	DO	F	N N	l	100	0 0			5494520
1N/985/4.: 50 S		KUKU EAST 2851657		1300 CB	RUNOFF		132A 330A B	R	D	B	F	N	- C	100	0 0			5494143
1N/985/4.9 700 S		KUKU EAST 2.01E+08		1400 CB	RUNOFF		132A 181AT	R	Ŵ	Ō		N	l	100	0 0			5493548
1N/985/5.4 1200 S		KUKU EAST 2.01E+08		1115 CB	RUNOFF		130A 412A F	R	D	В	F	N	L		0 0		1 1788783	
1N/985/7.9 500 S		NORTH MA 2853297		410 CB	RUNOFF		402A 410A F	R	W	DN	1	N	C C	100	0 0			5491149
1N/985/7.2 200 N		NORTH MA 2.01E+08		1731 CC	RUNOFF		136A 622A FP	R	D	DN	F	N	L L		0 1		1 1787668	
1N/985/7.! 50 S		NORTH MA 2.01E+08		1950 CC	RUNOFF		102A 130A FPV	R	D	DO	F	N	L	100	0 0			5491568
1N/985/6.: 2000 N		WAIKAWA 2754752		2202 DA	RUNOFF		137A 121B B	c	D	DO	, c	N	L	100	0 0			5492666
1N/985/6.! 60 S			5/02/2011 Sat	852 DA	RUNOFF		137A 1216 B 110A T	M	W	0	Г I	IN N	L		0 0			5492323
		WAIKAWA 2.01E+08 WAIKAWA 2.01E+08		852 DA 1820 DA	RUNOFF		131A 407A V	IVI E	W	0	L	IN N	L	100	0 0		2 1788053	
								E	W	0		IN N	c		1 0			
1N/985/6.7 200 S		WAIKAWA 2810073		1154 DA	RUNOFF		106A 359AT		VV	-	L F	IN	C					5492261
1N/985/6.7 280 N		WHAKAHO 2.01E+08		1357 DA	RUNOFF		130A 410A P	M	D	В	F	N	C C	100	0 0			5492235
1N/985/6.8 200 N		WHAKAHO 2850494		1912 DA	RUNOFF		130A EFS	M	vv	0	H	N	C C		0 0			5492176
1N/985/6.872	A	MANAKAU 2.01E+08	15/08/2011 Mon	429 DA	RUNOFF		135A 802 9G	E		DN	SF	N	C C	100	0 0			5492157
1N/985/6.8 150 N		WHAKAHO 2911919		2040 DA	RUNOFF		104A 111AT	M	VV	DN	н -	N	C		0 1			5492139
1N/985/7.(30 N		WHAKAHO 2.01E+08		1600 DA	RUNOFF		403A 801 B	M	W	0	F	N	L	100	0 0			5492041
1N/985/3.26	A	OHAU RLY 2950643		1035 DB	RUNOFF		132A 181A B	E	W	0	L -	N	C		0 0			5495212
1N/985/4.6 500 S		KUKU BEA(2950250		2125 DB	RUNOFF		911 TW	E	D	DN	F	N	C		0 0			5493822
1N/985/6.872	A	MANAKAU 2.01E+08		30 DB	RUNOFF		103A 110A B	E	W	DN	L -	N	C		0 0			5492157
1N/985/6.9 80 N		WHAKAHO 2.01E+08	6/11/2010 Sat	422 DB	RUNOFF		102A 111A PT	M	D	DN	F	N	L		0 0			5492086
1N/985/7.(30 S		WHAKAHO 2911117		2048 DB	RUNOFF		111A 632A FT	E	W	TN	L	N	L	100	0 0			5491985
1N/985/4.2 50 S		KUKU BEA(2856441		1228 EC		CN1C	370A 911 SWW	R	D	В	F	D N	С		0 0			5494271
1N/985/4.286	I	KUKU EAST 2754157		1930 EC	OTHER	VS1	370A 911 W	R	D	DO	F	T N	L	100	0 0			5494193
1N/985/5.: 1000 S		KUKU BEA(2.01E+08		2005 EC	OTHER	CN1	912 W	E	D	DO	F	N	L	100	0 0			5493415
1N/985/6.2 800 N		WHAKAHO 2955176		40 EC	OTHER	TS1	370A 821 TX	R	D	DN	FS	N	С	100	0 0			5492562
1N/985/6.872	A	MANAKAU 2.01E+08		1500 FA	OTHER	CN1C	181A	E	W	0	L	N	С	100	0 0		0 1787844	
1N/985/7.{ 270 N		WAIKAWA 2954417	21/08/2009 Fri	850 FA	OTHER	4S1CT	197A 191B 155C	R	D	0	F	N	L	100	0 0		0 1787460	5491268
1N/985/3.4 800 N		KUKU EAST 2755497	26/09/2007 Wed	1539 FD	OTHER	CN1TC	181A 927	R	D	В	F	D N	С	100	0 0		0 1789350	5494991
1N/985/3.4 500 N		KUKU BEA(2950637	20/02/2009 Fri	1052 FD	OTHER	CN1VC	331A 353A 901	R	W	0	Н	N	L	100	0 0		0 1789340	5494819
1N/985/4.: 100 S		KUKU EAST 2952862	19/06/2009 Fri	1920 FD	OTHER	TN1V	101A 331A	E	D	DN	F	N	L	100	0 0		0 1789292	5494093
1N/985/6.062	A	TATUM PA 2955196	5/10/2009 Mon	1059 FD	OTHER	CS1CCC	331A 927	R	D	0	F	D N	L	100	0 0		0 1788417	5492709
1N/985/6.8 50 N		MANAKAU 2.01E+08	13/12/2010 Mon	1452 FD	OTHER	CN1C	181A 191B	E	D	В	F	N	L	100	0 0		0 1787878	5492194
1N/985/6.872	A	MANAKAU 2.01E+08	22/05/2011 Sun	1600 FD	OTHER	4N1CC	110A 331A	М	W	0	L	N	L	100	0 0		0 1787844	5492157
1N/985/6.9 100 N		WHAKAHO 2850333	12/02/2008 Tue	730 FD	OTHER	4S1CV	181A	М	W	0	F	N	L	100	0 0		0 1787794	5492102
1N/985/7.047	I	WHAKAHO 2.01E+08	24/08/2011 Wed	820 FD	OTHER	CN1C	130A 181A 331A 80	800 R	W	0	F	T S	С	100	0 0		0 1787750	5492013
1N/985/7.2 200 S		WHAKAHO 2.01E+08	21/12/2010 Tue	1618 FD	OTHER	VN1V	181A 197B	R	W	0	L	N	С	100	0 0		0 1787678	5491827
1N/985/5.€ 1400 N		WHAKAHO 2.01E+08	30/04/2010 Fri	1626 GC	OTHER	TN1C	181A 171B 404B 80	01 9 R	W	0	Н	D N	L	100	0 0		0 1788679	5493031
1N/985/6.(1010 N		WHAKAHO 2853313	2/07/2008 Wed	1930 GC	OTHER	TN1C	160A 174B 372B 40	04B R	D	DO	F	D N	С	100	0 0		0 1788433	5492728
1N/985/4.5 400 S		KUKU BEA(2855127	30/09/2008 Tue	925 GE	OTHER	CN1O	155A 160A F	E	W	0	F	Ν	L	100	0 0		0 1789283	5493921
1N/985/6.521	А	WAIKAWA 2.01E+08	24/08/2010 Tue	1700 QG	OTHER	VN14	682A D	Е	D	В	F	Ν	С	100	0 0		0 1788127	5492357
1N/985/4.! 240 S		KUKU EAST 2711035	21/01/2007 Sun	1727 FD	OTHER	CS1CCC	331A 353A	R	W	0	L	Ν	С	100	0 0		1 1789284	5493953
1N/985/4.158	I.	KUKU BEA(2812206	7/06/2008 Sat	1213 JA	INTERSEC	T CN1C	302B 375B	R	W	0	L	T G	С	100	0 0		2 1789307	5494321
1N/985/5.! 1300 S		KUKU EAST 2754962	27/07/2007 Fri	515 MO	INTERSEC	T TS1	129A 603A FV	R	D	DN	F	Ν	L	100	0 0		0 1788720	5493082
1N/985/7.047	I.	WHAKAHO 2713763	28/11/2007 Wed	810 GC	OTHER	CS14	372B	М	D	В	F	T S	С	100	0 0		1 1787750	5492013
1N/985/6.9 50 N		WHAKAHO 2912061	22/05/2009 Fri	1003 QG			191A 170D	М	W	0	L	Ν	L		0 0		1 1787768	5492060


				Crashes					
Movement	#	%	F	S	м	N	Total		F+S Casualitie s (Dsi)
INTERSECTION	2	4%	0	0	1	0	1		0
HEADON	3	6%	1	1	1	0	3		3
RUNOFF	23	44%	1	2	9	12	24		3
OTHER	24	46%	0	0	3	21	24		0
total	52	100%	2	3	14	33	52		6



Appendix D Outline Plans



HALL GILLY BE USED FOR THE PURPOSE FOR WINCH THEY WERE SUPPLED. ANY RE-USE IS PROHESTED AND NO PART OF THIS DOCUMENT MAY BE REPRODUCED OR DISTORMETED COPY RIGHT O



ASK



Appendix E Cost Estimates

	Project Estimate - F Project Name: Otaki to Levi PFR 3 (Manakau - Ohau Option 3-1	n PFR Study		FE E					
ltem	Description	Base Estimate	Contingency	Funding Risk					
Α	Nett Project Property Cost	4,000,000	800,000	1,320,000					
	Investigation and Reporting - Consultancy Fees - NZTA-Managed Costs	1,111,000 0	222,200 0	366,600 0					
В	Total Investigation and Reporting	1,111,000	222,200	366,600					
	Design and Project Documentation - Consultancy Fees - NZTA-Managed Costs	2,381,000	476,200 0	785,700					
С	Total Design and Project Documentation	2,381,000	476,200	785,700					
	Construction MSQA - Consultancy Fees - NZTA-Managed Costs	2,381,000 0	476,200 0	785,700 0					
	- Consent Monitoring Fees Sub Total Base MSQA	0 2,381,000	0 476,200	0 785,700					
D2 D3 D4 D5 D6 D7 D8 D9 D10 D11 D12 D13 D D E F G Project Pr Investiga Design au	Physical Works Environmental Compliance Earthworks Ground Improvments Drainage Pavement and Surfacing Bridges / Structures Retaining Walls Traffic Services Service Relocations Landscaping Traffic Management and Temporary Works Preliminary and General Extraordinary Construction Costs Sub Total Base Physical Works Total Construction & MSQA Project Base Estimate roperty Cost Expected Estimate roperty Cost Expected Estimate mod Reporting Expected Estimate nd Project Documentation Expected Estimate	1,600,000 3,445,000 235,000 4,237,000 12,930,000 900,000 922,500 1,687,500 690,000 2,000,000 3,000,000 31,747,000 34,128,000 (A+B+C+D) (E+F)	320,000 1,033,500 20,000 47,000 847,400 2,586,000 180,000 184,500 337,500 138,000 400,000 600,000 0 6,693,900 7,170,100 8,668,500 50,288,500 4,800,000 1,33,200 2,857,200 41,298,100	528,000 1,722,500 33,000 77,600 1,398,200 4,266,900 297,000 304,400 556,900 227,700 660,000 990,000 0 11,062,200 11,847,900					
Construc H	14,320,200								
H Funding Risk (Assessed / Analysed) (A+B+C+D) I 95 th Percentile Project Estimate (G+H)									
Project Pr Investiga Design ar	roperty Cost 95th Percentile Estimate tion and Reporting 95th Percentile Estimate nd Project Documentation 95th Percentile Estimate tion 95th Percentile Estimate			64,608,700 6,120,000 1,699,800 3,642,900 53,146,000					

Base Date of Estimate	13 Nov 2012	Cost Index
Estimate prepared by:	Ben Dodgshun	Signed
Estimate internal peer review by:	Marten Oppenhuis	Signed
Estimate external peer review by:		Signed
Estimate approved by NZTA Project Manager:		Signed

Note: (1) These estimates are exclusive of escalation and GST.

	Project Estimate - F Project Name: Otaki to Levi PFR 3 (Manakau - Ohau Option 3-2	n PFR Study		FE Feasibility Estimate						
Item	Description	Base Estimate	Contingency	Funding Risk						
А	Nett Project Property Cost	5,000,000	1,000,000	1,650,000						
	Investigation and Reporting - Consultancy Fees - NZTA-Managed Costs	743,000 0	148,600 0	245,200 0						
В	Total Investigation and Reporting	743,000	148,600	245,200						
с	Design and Project Documentation - Consultancy Fees - NZTA-Managed Costs Total Design and Project Documentation	1,592,000	318,400 0	525,400 0						
C		1,592,000	318,400	525,400						
	Construction MSQA - Consultancy Fees - NZTA-Managed Costs	1,592,000 0	318,400 0	525,400 0						
	- Consent Monitoring Fees Sub Total Base MSQA	0 1,592,000	0 318,400	0 525,400						
D2 D3 D4 D5 D6 D7 D8 D9 D10 D11 D12 D13 D D E F	Physical Works Environmental Compliance Earthworks Ground Improvments Drainage Pavement and Surfacing Bridges / Structures Retaining Walls Traffic Services Service Relocations Landscaping Traffic Management and Temporary Works Preliminary and General Extraordinary Construction Costs Sub Total Base Physical Works Total Construction & MSQA Project Base Estimate (A+B+C+D) Contingency (Assessed / Analysed) Project Expected Estimate	1,600,000 1,925,000 100,000 172,000 4,259,000 6,750,000 0 550,500 1,687,500 683,000 1,000,000 2,500,000 0 21,227,000 22,819,000 30,154,000 (A+B+C+D) (E+F)	320,000 577,500 20,000 34,400 851,800 1,350,000 0 110,100 337,500 136,600 200,000 500,000 0 4,437,900 4,756,300 6,223,300 36,377,300	528,000 962,500 33,000 56,800 1,405,500 2,227,500 0 181,700 556,900 225,400 330,000 825,000 0 7,332,300 7,857,700						
Investiga Design ai Construc	roperty Cost Expected Estimate tion and Reporting Expected Estimate nd Project Documentation Expected Estimate tion Expected Estimate		6,000,000 891,600 1,910,400 27,575,300							
H	Funding Risk (Assessed / Analysed)		(A+B+C+D)	10,278,300 46,655,600						
Investiga Design ai										

Base Date of Estimate	13 Nov 2012	Cost Index
Estimate prepared by:	Ben Dodgshun	Signed
Estimate internal peer review by:	Marten Oppenhuis	Signed
Estimate external peer review by:		Signed
Estimate approved by NZTA Project Manager:		Signed

Note: (1) These estimates are exclusive of escalation and GST.



Appendix F Economic Analysis Worksheets



Simplified Procedure 3 - General Road Improvements

GENERAL ROADING IMPROVEMENT WORKS: EVALUATION SUMMARY

WORKSHEET 1

1	Evaluator(s)	Oliver Brown											
	Reviewer(s)	David Wanty	1										
•	B	D · · · ·											
2	Project / Pack		_										
	Approved Orga		e		NZTA	a vina i	Manakaw	Dhavi Drideraa					
	Project / Packa Your Reference				8050080		ivianakau (Dhau Bridges	PFR				
	Project Descrip				Safety In		monte						
	Describe the p		addresse		Reduce of								
	Describe the p			ŭ		Jiudile	0						
3	Location												
	Brief description	on of location	State H	ighway	1, north o	of Otak	ki, 200m so	outh of the cen	tral point of th	e Manuka	au Railway		
			Overbri	dge to a	200m nor	th of th	ne Ohau R	ver bridge, RF	P 1/985/3.00 to	1/985/7	.95		
4	Alternatives a	-		D				1 6 116					
	Describe the D			Do no	tning - rep	blace b	ridges at e	end of life					
	Summarise the	e options asse	ssed	Option	1 · Realic	nmen	t and wide	ning of highwa	ay with TL4 WF	3B and n	ew bridae s	tructu	ires
									y line with TL4				
				structu		3u	, real par		,	_ an		,-	
5	Timing												
	Time Zero (ass)		1 July 20	013					
	Expected dura	tion of constru	iction (M	onths)			12						
e	Economia Eff	iolonov											
6	Economic Eff Date economic		molotod	(mm/v	مممرا	14	5 Novembe	or 2012					
	Base date for o		Inpleted	(11111/y	ууу)	1.	1 July 20						
	AADT at Time				-		16128						
	Traffic Growth		Zero (%)	-		1.2%						
		riato at rimo	2010 (70	/	-								
	Existing Rough	nness		2.70) IF	RI or N	AASRA	Existing Traf		90	km/hr (e	est)	
	Predicted Roug			2.70) IF	RI or N	AASRA	Predicted Tra			km/hr		
	Length of Job				4.95		km	Posted Spee	ed Limit		km/hr		
	Length of Job		ments		4.99		km	Road Type		Rural S	trategic		
	Length of new		,		3.20		km		ore Improvem		- 3%		
	Length of exist	ting highway u	ised		1.79)	km	Gradient Afte	er Improvemer	nts <mark>1</mark>	- 2%		
7	PV Cost of Do	o Minimum						Cost \$	\$2	,177,899		Α	
8	PV Cost of the	e preferred O	ption					Cost \$	\$50	0,649,623	}	В	
9	Benefit values	s from Works	heet 4, s	5 or 6									
	PV Travel Time	e Cost saving	s: \$	\$3,	733,018	С	x Update	Factor [™]	1.33	= \$	\$4,964,9	14	W
	PV VOC & CO	2 savings:	\$	-\$2,	,581,260	D	x Update	Factor	1.04	= \$	-\$2,684,5	10	Y
								40					
	PV Accident C	ost savings:	\$	\$11	,037,396	E	x Update	Factor	1.17	= \$	\$12,913,7	'53	_ Z
						_		- 40					
	PV Passing La	ine savings:	\$	\$2,	801,132	F	x Update	-actor ~	1.00	= \$	\$2,801,1	32	_ X
10	B/C Ratio =	W + Y + Z + X	(_	BENEF	PTI	64011	+ -268/51	0 + 12913753	8 ± 28011' =				٦
10						04314			$\frac{3+28011}{5}$ =		0.4		
		B - A		COST	3		506496	23 - 2177899					

11 FYRR =	<u>1st Year BENEFITS</u>	=	[(4964914+-2684510)/12.09+12913753/10.97] x 0.9259	=	0.03	
	COSTS		50649623 - 2177899	-		




Simplified Procedure 3 - General Road Improvements

GENERAL ROADING IMPROVEMENT WORKS: EVALUATION SUMMARY

WORKSHEET 1

1	Evaluator(s) Oliver Brown	
	Reviewer(s) David Wanty	
2	Project / Package DetailsApproved Organisation NameNZTAProject / Package NameOtaki to Levin: Manakau OYour Reference80500802Project DescriptionSafety ImprovementsDescribe the problem to be addressedReduce crashes	Dhau Bridges PFR
3	Location Brief description of location State Highway 1, north of Otaki, 200m so Overbridge to 200m north of the Ohau Riv	
4		allel to railway line with TL4 WRB and new bridge
5	Timing Time Zero (assumed construction start date) Expected duration of construction (Months)	
6	Economic Efficiency Date economic evaluation completed (mm/yyyy) Base date for costs AADT at Time Zero Traffic Growth Rate at Time Zero (%) Existing Roughness Predicted Roughness Length of Job Before Improvements Length of Job After Improvements 4.70 km	Existing Traffic Speed 90 km/hr (est) Predicted Traffic Speed 100 km/hr Posted Speed Limit 100 km/hr Road Type Rural Strategic
7	Length of new highway 4.70 km Length of existing highway used 0.00 km PV Cost of Do Minimum 0.00 km	Gradient Before Improvements 1 - 3% Gradient After Improvements 1 - 2% Cost \$ \$2,177,899
8	PV Cost of the preferred Option	Cost \$\$36,759,536 B
9	Benefit values from Worksheet 4, 5 or 6 PV Travel Time Cost savings: \$	Factor ^{TT} 1.33 = \$ \$17,611,830 W
	PV VOC & CO2 savings: \$\$5,046,088 D x Update F	Factor ^{VOC} 1.04 = \$ \$5,247,932 Y
	PV Accident Cost savings: \$ \$11,726,776 E x Update F	
	PV Passing Lane savings: \$ \$2,558,452 F x Update F	
10		12 + 13720327 + 25584 = 36 - 2177899 1.1





Appendix G Bridge Condition Data

Not TRANSPORT ACENCY Ohau (SH1) Bridge 1 Bridge Type: RC T-beam, monolithic abuts. Status took Map Ref: 2000 Cambodier and the status of the					Bridg							Highway	/:	BCI(Av):	р.
Extern code		7	NZ TRANSPOF WAKA KOTAHI	RT AGENCY	Ohau	ı (S⊦	11) Bric	lge				1				1/2
A = No defect C = Moderate, 5 - 20% 1 = as rise/ defect 3 = as rise/ defect 1 = as rise/ defect Deck width: 3 = noderate, 5 - 20% 7.40m/ Last insp. by: Spans: 0///Last 1/10.4 Last insp. by: CB 22//CB b = Wide, 20 - 50% 3 = moderate defect 4 = several defect 4 = several defect 4 = several defect 4 = several defect 5 = 0.00% Note: 1/10.7 8/14.3 1/10.4 Last insp. by: CB 22//CB b = Wide, 20 - 50% 5 = moderate defect 4 = several defect 4 = several defect 3 = moderate defect 5 = 50% Inspector: CRG Next Inspector: Next Inspector: Next Inspector: CG S c = Moderate defect 4 = Hatticitatic 5 Service SR Brief description of fault and comments Wertical cracking to beams up to 0.3mm wide, and small spall to Hi 1 (see photo) Next Historical cracking to beams up to 0.3mm wide to softi of deck coverhang c = Service 6 Parapet beam or cantilever C 3 s Vertical cracking to deping on linkages c = Service 8 Foundations A 1 1 1 2 Secumulation of bird droppings on linkages 1 1 1 2 Secumulation of bird droppings on linkages 1 1 1 <td>Bridg</td> <td>je Ty</td> <td>уре:</td> <td>RC T-be</td> <td>am, mo</td> <td>onolith</td> <td>nic abuts</td> <td>6.</td> <td></td> <td></td> <td></td> <td></td> <td></td> <th></th> <td></td> <td></td>	Bridg	je Ty	уре:	RC T-be	am, mo	onolith	nic abuts	6.								
B Nois 5% D 2 = early sign of Span: Deckwidth: / .40m/ Owner: Commercial Cast map. Add: 2201 Ext = Extent: Sware defect 5 = element faile Span: 1/10.7 8/14.3 1/10.4 Last map. dat: 2201 GB Ext = Extent: Sware defect 5 = element Span: 1/10.7 8/14.3 1/10.4 Last map. dat: 2201 GB Mant: S-Structural, Report Type Imspector: GRG Next Inspector:			-	-			BSN:			9880		Map Ref:				
Commoderate 5 - 20% defect Span: of Last insp. due: 22/01 De Wide; 20:0% 5 = severe defect 5 = severe defect 5 = severe defect 6 = severe defect 7 = severe defect 1 = severe defect 7 = severe defect 8 = severe defect	-					D	eck width	:		7.40m/		Owner:				
E = > 50% 4 = source offect 5 = element failed 1000 / 00 / 00 / 00 / 00 / 00 / 00 / 00					S	pan:		of			Last Insp. date: 22/01/200					
Set element failed Total bridge length: 135.00m Report Type (01(22/DS)): (01(22/DS)): G2 Ext = Extent : Sev Severity Maint : S-Structural: R-Routine Inspector: GRG Next Inspection: Set Inspection: Next Inspection: Stat No Description Ext Sev S/R Brief description of fault and comments Stat No Description Ext Sev S/R Brief description of fault and comments 2 Sec. ele Transverse beams C 3 S Vertical cracking to beams up to 0.3mm wide, and small spall to VII at (see photo). 4 H at pints P C 3 S Toransverse cracking to beams up to 0.3mm wide to softit of deck vertical cracking to diaphragms up to 0.2mm wide 6 Parapet beam or cantilever C 3 S Toransverse/diagonal cracking to diaphragms up to 0.2mm wide 7 Cross bracing A 1 P P 10 Head wall A 1 P 11 Pier / column C 3 S Parapetion cracking to apint of pier 1 (see pho			20 - 50%			t S	pans:	1/1	0.7 8/	4.3 1/10.4		Last insp. by: GB				
Ext = Extent : Sev - Severity Inspector: GRG Next Main: : S-Structural: B-Routine Date: 10/02/2011 Inspection: Set No Description Ext Sev S/R Brief description of fault and comments Vertical cracking to beams up to 0.3mm wide, and small spall to 1 Hu at (see photo) Hu at (see photo) Hu at (see photo) 2 Sec. ele- Transverse beams - - Hu at (see photo) 2 Sec. ele- Transverse beams - - - 4 Hail joints - - - - 5 Sistemic linkages B 2 S Accumulation of bird droppings on linkages 6 Paraget beam or cantilever C 3 S Vertical cracking to diaphragms up to 0.2mm wide 7 Cross bracing B 2 S Vertical cracks to CL of piers B.C.D.E.F. and J up to 1.0mm wide spalls to toy of pile cap pier H (see photo) 11 Heat / anage A 1 - 12 Cross-head / capping beam A 1 - 13 <td>= = > 5</td> <td>50%</td> <td></td> <td></td> <td></td> <td>т</td> <td>otal brida</td> <td>o longth</td> <td></td> <td>135.00m</td> <td></td> <td colspan="5">Report Type G2</td>	= = > 5	50%				т	otal brida	o longth		135.00m		Report Type G2				
Maint: S-Structural; R=Routine Date: 10//02/2011 Inspection: Image: Second Control of Control of Control of Control of Control Contrel Control Control Contrel Control Control Contre		_					-	-		100.0011		(G1/G2/D/S):				
Element Ext Sev S/R Brief description of fault and comments Set No Description Ext Sev S/R Brief description of fault and comments Set No Description C 3 S Vertical cracking to beams up to 0.3mm wide, and small spall to H1 at 1 (see photo) Set Soc.ete Transverse beams C 2 S Longitudinal and transverse cracking to deck soffit up to 0.2mm wide Set Setsmic linkages B 2 S Accumulation of bird droppings on linkages Set Parapot beam or cartilever C 3 S Overlical cracking to diaphragms up to 0.3mm wide to soffit of deck 9 Abutments A 1 Pirapot beam or cartilever C 3 S Overlical cracking to diaphragms up to 0.3mm wide to soffit of deck 9 Abutments A 1 Pirapot beam or cartilever C 3 S photo 10 Head wall Vertical cracking to top of pile cap piler H (see photo) and to wall of piler 1 (se photo) 12 Cross-head / capping beam A			-		-											
Set No. Description Ext Sev S/H Errer description of fault and comments and the second of the	,	,	,	Routine		Date	: 10/02/	2011	1			Inspection	on:			
Primary element C 3 S Vertical cracking to beams up to 0.3mm wide, and small spall to 1/H at 1 (see photo) 2 Sec. ele- 3 Transverse beams 0/H at 1 (see photo) Longitudinal and transverse cracking to deck soffit up to 0.2mm wide to 0.3mm wide, and small spall to 1/H at 1 (see photo) 4 H at 1 joints - - - - 4 H at 1 joints - - - - 5 Seismic linkages B 2 S Accumulation of bird droppings on linkages overhang - 7 Cross bracing B 2 S Vertical cracking to diaphragms up to 0.3mm wide to soffit of deck overhang 9 Abutments A 1 - - 11 Pier / column C 3 S spalls to top of pier spice - 12 Cross-head / capping beam A 1 - - - 13 Bearing plinth / shelf - - - - - 14 Bearing substructure drainage A 1 - -			-			Ext	Sev	S/R		Brief descri	iption o	of fault an	d co	omment	S	
Open Part of a primary seturation C S S H' at I (see photo) 2 Sec, etc. Transverse beams - - - 3 ment(s) Other C 2 S Longitudinal and transverse cracking to deck soffit up to 0.2mm vide 4 Half joints - - - - - 4 Half joints - - - - - 6 Parapt beam or cantilever C 3 S - - 7 Cross bracing B 2 S Vertical cracking to diaphragms up to 0.2mm wide - 8 Foundations A 1 - - - 10 Head wall - - - - - 11 Pier / capping beam A 1 - - - 12 Cross-head / capping beam A 1 - - - 13 Bearing plinth / shelf - -	et r	No	Descriptio	n					Vortical	araaking to been	-	Omm wide	and a	mallanall	o D	1 0000
Provide 2 See, etc. (other Transverse beams (other C 2 S Longitudinal and transverse cracking to deck soffit up to 0.2mm vide 5 Seismic linkages B 2 S Accumulation of bird droppings on linkages 7 Corso bracing B 2 S Accumulation of bird droppings on linkages 7 Corso bracing B 2 S Vertical cracking to diaphragms up to 0.3mm wide to soffit of deck overhang. 8 Foundations A 1 Corso bracing B 2 S Vertical cracking to diaphragms up to 0.3mm wide to soffit of deck overhang. 9 Abutments A 1 Corso bracing A 1 Corso bracing C 3 S Vertical cracking to diaphragms up to 0.2mm wide to soffit of deck overhang. 10 Head wall C 3 S Vertical cracking to diaphragms up to 0.2mm wide to soffit of leck overhang. 11 Pier / column C 3 S Vertical cracking to Cl.0 piers B, C.D.E.F. and J up to 1.0mm wide spalls to top of pie cap pier H (see photo) and to wall of pier (second vide vide vide vide vide vide vide vid		1	Primary elem	ent		С	3	S	H/I at I	(see photo)	is up to u	.3mm wide, a	and s	mail spail	.0 B4	i span
T Cross bracing B 2 S Vertical cracking to diaphragms up to 0.2mm wide 8 Foundations A 1 Vertical cracking to diaphragms up to 0.2mm wide 9 Abutments A 1 Vertical cracks to CL of piers B,C,D,E,F, and J up to 1.0mm wide spalls to top of pile cap pier H (see photo) and to wall of pier 1 (see photo) 11 Pier / column C 3 S Vertical cracks to CL of piers B,C,D,E,F, and J up to 1.0mm wide spalls to top of pile cap pier H (see photo) and to wall of pier 1 (see photo) 12 Cross-head / capping beam A 1 Vertical cracks to CL of pile cap pier H (see photo) and to wall of pier 1 (see photo) 13 Baarings - - - - 14 Bearings - - - - 15 Superstructure drainage A 1 - - 17 Movement / expansion joints C 3 S Reflective cracking to expansion joint (see photo) 18 Painting: Substructure elements - - - - 20 Painting: Superstructure C		2	Sec. ele- T	ransverse b	eams					()						
T Cross bracing B 2 S Vertical cracking to diaphragms up to 0.2mm wide 8 Foundations A 1 Vertical cracking to diaphragms up to 0.2mm wide 9 Abutments A 1 Vertical cracks to CL of piers B,C,D,E,F, and J up to 1.0mm wide spalls to top of pile cap pier H (see photo) and to wall of pier 1 (see photo) 11 Pier / column C 3 S Vertical cracks to CL of piers B,C,D,E,F, and J up to 1.0mm wide spalls to top of pile cap pier H (see photo) and to wall of pier 1 (see photo) 12 Cross-head / capping beam A 1 Vertical cracks to CL of pile cap pier H (see photo) and to wall of pier 1 (see photo) 13 Baarings - - - - 14 Bearings - - - - 15 Superstructure drainage A 1 - - 17 Movement / expansion joints C 3 S Reflective cracking to expansion joint (see photo) 18 Painting: Substructure elements - - - - 20 Painting: Superstructure C	ents	3	ment(s) C	Other		С	2	S	Longitu	dinal and transver	rse crack	ing to deck s	offit u	ip to 0.2mr	n wi	de
T Cross bracing B 2 S Vertical cracking to diaphragms up to 0.2mm wide 8 Foundations A 1 Vertical cracking to diaphragms up to 0.2mm wide 9 Abutments A 1 Vertical cracks to CL of piers B,C,D,E,F, and J up to 1.0mm wide spalls to top of pile cap pier H (see photo) and to wall of pier 1 (see photo) 11 Pier / column C 3 S Vertical cracks to CL of piers B,C,D,E,F, and J up to 1.0mm wide spalls to top of pile cap pier H (see photo) and to wall of pier 1 (see photo) 12 Cross-head / capping beam A 1 Vertical cracks to CL of pile cap pier H (see photo) and to wall of pier 1 (see photo) 13 Baarings - - - - 14 Bearings - - - - 15 Superstructure drainage A 1 - - 17 Movement / expansion joints C 3 S Reflective cracking to expansion joint (see photo) 18 Painting: Substructure elements - - - - 20 Painting: Superstructure C	me															
T Cross bracing B 2 S Vertical cracking to diaphragms up to 0.2mm wide 8 Foundations A 1 Vertical cracking to diaphragms up to 0.2mm wide 9 Abutments A 1 Vertical cracking to diaphragms up to 0.2mm wide 9 Abutments A 1 Vertical cracks to CL of piers B,C,D,E,F, and J up to 1.0mm wide spalls to top of pile cap pier H (see photo) and to wall of pier 1 (see photo) 11 Pier / column C 3 S Vertical cracks to CL of piers B,C,D,E,F, and J up to 1.0mm wide spalls to top of pile cap pier H (see photo) and to wall of pier 1 (see photo) 12 Cross-head / capping beam A 1 - 13 Bearings - - - 14 Bearing is ubstructure drainage A 1 - 15 Superstructure drainage A 1 - 16 Substructure drainage A 1 - 17 Movement / expansion joints C 3 S Reflective cracking to expansion joint (see photo) 18 Painting: substructure elements - - - - -	Ë	5	Seismic linka	ges		В	2	S						(f)) ()		
7 Cross bracing B 2 S Vertical cracking to diaphragms up to 0.2mm wide 8 Foundations A 1		6	Parapet beam	n or cantileve	er	С	3	S			скing up t	o 0.3mm wid	e to s	sottit of dec	ĸ	
8 Foundations A 1 9 Abutments A 1 9 Abutments A 1 10 Head wall 11 Pier / column C 3 S Vertical cracks to CL of piers B,C,D,E,F, and J up to 1.0mm wide spalls to top of pile cap pier H (see photo) and to wall of pier I (see photo) 11 Pier / column C 3 S Vertical cracks to CL of piers B,C,D,E,F, and J up to 1.0mm wide spalls to top of pile cap pier H (see photo) and to wall of pier I (see photo) 12 Cross-head / capping beam A 1 13 Bearing Birth / shelf 14 Bearing Birth / shelf 15 Superstructure drainage A 1 16 Substructure drainage A 1 20 Painting: substructure elements C 3 S R 21 Access / walkways / gartries C 3 R Concrete handrails only along bridge 22		7	Cross bracino	a		В	2	S		0	ragms ur	o to 0.2mm w	/ide			
10 Head wall C 3 S Vertical cracks to CL of piers B,C,D,E,F, and J up to 1.0mm wide spalls to top of pile cap pier H (see photo) and to wall of pier I (see photo) 11 Pier / column C 3 S spalls to top of pile cap pier H (see photo) and to wall of pier I (see photo) 12 Cross-head / capping beam A 1 photo) 13 Bearings - - - 14 Bearing plinth / shelf - - - 15 Superstructure drainage A 1 - 16 Painting: Superstructure elements - - - 19 Painting: barters/guardrails B 2 R Lichen growing on handrails 22 Guardrail / handrail / safety fences - - - - 23 Guardrail / handrail / safety fences - - - - 24 Footbary / verge / footbridge surfacing A 1 - - - 24 Surfacing A 1 - - - - - 25 Invert / /ver bed <t< td=""><td></td><td>8</td><td></td><td>5</td><td></td><td>Α</td><td>1</td><td></td><td></td><td>0 1</td><td>0 1</td><td></td><td></td><th></th><td></td><td></td></t<>		8		5		Α	1			0 1	0 1					
13 Bearings		9	Abutments			Α	1									
13 Bearings	nre	10	Head wall													
13 Bearings	struct	11	Pier / column			С	3	s	spalls to							
13 Bearings Image: Construction of the second seco	qn	12	Cross-head /	capping bea	ım	А	1		p/10(0)							
Image: Note of the image o	<u>ہ</u>			11 0												
Image: Structure drainage A 1 17 Movement / expansion joints C 3 S Reflective cracking to expansion joint (see photo) 18 Painting: Superstructure elements Image: Superstructure elements Image: Superstructure elements Image: Superstructure elements 19 Painting: barriers/guardrails B 2 R Lichen growing on handrails 20 Painting: harriers/guardrails B 2 R Lichen growing on handrails 21 Access / walkways / gantries Image: Superstructure elements Image: Superstructure elements Image: Superstructure elements 22 Guardrail / handrail Safety C 3 R Concrete handrails only along bridge 23 Carriageway surfacing C 3 R Settlement and cracking to asphalt of increasing lane abut A app 4 Footway / verge / footbridge A 1 Image: Surfacting 24 Footway / verge / footbridge A 1 Image: Surfacting 25 Invert / river bed A 1 Image: Surfacting Im	-	14	Bearing plinth	n / shelf												
Image: Note of the system o	_					Α										
10 10 10 10 10 10 10 20 Painting: barriers/guardrails B 2 R Lichen growing on handrails 21 Access / walkways / gantries	ts _										<u> </u>					
10 1 antring. Substructure (section of b) B 2 R Lichen growing on handrails 21 Access / walkways / gantries	ner –	17			nts	С	3	S	Reflecti	ve cracking to exp	pansion jo	oint (see pho	to)			
10 1 antring. Substructure claiments B 2 R Lichen growing on handrails 21 Access / walkways / gantries	len	18		erstructure												
21 Access / walkways / gantries		19	Painting: sub	structure ele	ments											
Appendix C 3 R Concrete handrails only along bridge 23 Carriageway surfacing C 3 R Settlement and cracking to asphalt of increasing lane abut A app 24 Footway / verge / footbridge surfacing A 1 25 Invert / river bed A 1 26 Aprons A 1 27 Aggradation B 2 S Bed level may be at bottom of skirts at piers - MONITOR 28 Degradation B 2 S Bed level may be at bottom of skirts at piers - MONITOR 29 Scour C 3 R Minor debris on piers H and I 30 River banks A 1 31 Revetment / batter slope paving A 1 32 Wing walls A 1 33 Retaining walls A 1 34 Embankments A 1 35 Approach rails / barriers / walls A 1 36 Signs <td< td=""><td>2</td><td>20</td><td>Painting: barr</td><td>riers/guardra</td><td>ils</td><td>В</td><td>2</td><td>R</td><td>Lichen</td><td>growing on handra</td><td>ails</td><td></td><td></td><th></th><td></td><td></td></td<>	2	20	Painting: barr	riers/guardra	ils	В	2	R	Lichen	growing on handra	ails					
24 surfacing A 1 A 1 25 Invert / river bed A 1 A	6	21														
24 surfacing A 1 A 1 25 Invert / river bed A 1 A	ant	22		andrail / safe	ty	С	3	R	Concre	e handrails only a	along brid	lge				
24 surfacing A 1 A 1 25 Invert / river bed A 1 A	Ĩ.	23		surfacing		С	3	R	Settlem	ent and cracking	to asphal	t of increasin	g lan	e abut A a	ppro	ach
2-4 surfacing A 1 Image: constraint of the second s	Ĕ,		Footway / ver		ge								J			
A 1 Image: constraint of the state	4		surfacing	-				 								
30 River banks A 1 30 River banks A 1 31 Revetment / batter slope paving A 1 32 Wing walls A 1 33 Retaining walls A 1 34 Embankments A 1 35 Approach rails / barriers / walls A 1 36 Signs A 1 37 Lighting	<u>6</u>			bed				. <u> </u>								
30 River banks A 1 30 River banks A 1 31 Revetment / batter slope paving A 1 32 Wing walls A 1 33 Retaining walls A 1 34 Embankments A 1 35 Approach rails / barriers / walls A 1 36 Signs A 1 37 Lighting	ants															
30 River banks A 1 30 River banks A 1 31 Revetment / batter slope paving A 1 32 Wing walls A 1 33 Retaining walls A 1 34 Embankments A 1 35 Approach rails / barriers / walls A 1 36 Signs A 1 37 Lighting	Juc 2							S	Bed lev	el may be at botto	om of skir	ts at piers - N	IONI	TOR		
30 River banks A 1 30 River banks A 1 31 Revetment / batter slope paving A 1 32 Wing walls A 1 33 Retaining walls A 1 34 Embankments A 1 35 Approach rails / barriers / walls A 1 36 Signs A 1 37 Lighting	E															
35 Approach rails / barriers / walls A 1 36 Signs A 1 37 Lighting										· · · · ·						
35 Approach rails / barriers / walls A 1 36 Signs A 1 37 Lighting	uts			batter slope	paving	А										
35 Approach rails / barriers / walls A 1 36 Signs A 1 37 Lighting	Jen		-			А	1									
35 Approach rails / barriers / walls A 1 36 Signs A 1 37 Lighting	len															
36 Signs A 1 37 Lighting																
37 Lighting	_			s / barriers /	walls											
			-			А	1									
						٨	1									
								R	Minor a	raffiti						
	- H		Junit			5			ioi g							

	Bridge Name:	Highway:	BCI(Av):	5
NZ TRANSPORT AGENCY WAKA KOTAHI	Ohau (SH1) Bridge	1		р. 2/2

		Comments and Recommendations for Maintenance/Repairs		
Item No.	Element No.	Suggested Remedial Work	Priority (H/M/L)	Estimated Cost
1	23	Level and reseal approach locally	М	\$1,000
2	22	Install guardrailing along bridge	М	\$40,000
3	17	Cut asphalt out and replace with Thormajoint	М	\$10,000
4	29	Remove debris	L	\$ 800
5	1	Epoxy inject cracks 0.2mm and wider	М	\$30,000
6	1	Repair spall	L	\$1,000
7	6	Epoxy inject cracks 0.2mm and wider	L	\$20,000
8	11	Repair spalls	L	\$5,000
9	11	Epoxy inject cracks 0.2mm and wider	М	\$10,000
10				
		Total Constru	uction Cost	\$117,800

 Remedial work recommended in last inspection has been completed:
 Yes
 (comment below if NO)

 NZTA Database changes required:
 Yes
 (Describe change below if answer is YES)

 Guardrail corrected
 Comments & Recommendations Relating to Future Management (Transfer to current report)

Inspection by : GRG - Bloxam Burnett & Olliver Limited

Date 10/02/2011

Date

Report examined by :

Version: 29 April 2011

4		NZ TRANSPOI Waka kotahi	RT AGENCY	Bridg Ohau		me: il Overb	oridge)			Highwa 1	y:	BCI(Av):	р. 1/2
Brid	lge T	уре:	RC port	al struct	ure									
	nt coo		Severity	code		BSN:			9883		Map Ref:			
	No def		1 = as ne		D	eck width			7.32m/		Owner:			
	Not > 5	o% ate; 5 - 20%	2 = early defect	signs of		pan:	•	of	7.02111/		Last Insp.	data	· 22/01	/2009
		20 - 50%	3 = mode	rate defe		•	1/9.6			Last insp. by:		. <u>22/01</u> GB	/2005	
	> 50%		4 = sever		3	pans:								
			5 = eleme	ent failed	Т	otal bridge	elength: 9.60m			Report Ty (G1/G2/D/S		G2		
Ext :	= Exte	nt ; Sev = Sev	verity		Insp	ector: 0	GRG				Next	,		
Main	t.: S =	Structural; R=	Routine			: 9/02/2					Inspecti	on:		
	leme				_			1			-			
Set	No	Descriptio	on		Ext	xt Sev	S/R		Brief descr	ription o	f fault an	id c	omments	
001					0	_		Longitu	dinal constructior	n joints alo	ng soffit of s	struct	ure are leakin	g with
re	1	Primary elem	ient		С	2	S	efflores		,	0			0
ctu ts	2	Sec. ele- T	Fransverse b	eams										
en	3		Other											
perstructu Elements	4	Half joints												
Superstructure Elements	5	Seismic linka												
SL	6	Parapet bean		er	А	1								
	7	Cross bracing	g											
	8	Foundations			А	1								
Load-bearing Substructure	9	Abutments			С	3	S		cracks to abutm up to 0.1mm wide		p to 0.8mm	wide	e, and horizont	al
etu	10	Head wall						CIACKS		e.				
-be	11	Pier / column	ı											
ad- bs	12		capping beam											
Su	13	Bearings	oupping bot											
	14	Bearing plinth	h / shelf											
	15	Superstructu												
50	16	Substructure			Α	1								
ilit) nts	17	Movement / e	Ū,	ints										
Durability Elements	18	Painting: Sup												
		elements												
	19	Painting: sub												
	20	Painting: barr			Α	1		I						
6	21	Access / walk												
it v	22	Guardrail / ha fences	andrail / safe	ety	А	1								
Safety lements	23	Carriageway	surfacing	ł	А	1		∦						
Ele S		Footway / ver		lae				1						
	24	surfacing			A	1								
	25	Invert / river b	bed											
/ay hts	26	Aprons												
Waterway Elements	27	Aggradation												
/ate	28	Degradation						I						
ЗШ	29	Scour				<u> </u>								
	30	River banks	h attau 1			<u> </u>		I						
Retaining Elements	31	Revetment /	patter slope	paving										
aini	32	Wing walls			С	2	S	⊢ine ve	rtical and diagon	al cracking	to wingwal	IS		
ler.	33	Retaining wa												
ωш	34	Embankment			A	1								
	35	Approach rail	Is / barriers /	walls	A	1								
5	36	Signs			A	1								
Other	37	Lighting												
Ô	38	Services			A	1		N .						
	39	Graffiti			В	2	R	Modera	te amount of offe	ensive grafi	ITI			
							l	l						

NZ TRANSPORT AGENCY	Bridge Name: Ohau Rail Overbridge	Highway: 1	BCI(Av):	р. 2/2
	3			

		Comments and Recommendations for Maintenance/Repairs		
Item No.	Element No.	Suggested Remedial Work	Priority (H/M/L)	Estimated Cost
1	9	Epoxy inject vertical cracks greater than 0.2mm wide	L	\$20,000
2				
3				
4				
5				
6				
7				
8				
9				
10				
		Total Constru	uction Cost	\$20,000

Remedial work recommended in last inspection has been completed: Yes (comment

No

(comment below if NO)

(Describe change below if answer is YES)

NZTA Database changes required:

Comments & Recommendations Relating to Future Management (Transfer to current report)

Inspection by :	GRG - Bloxam Burnett & Olliver Limited	Date	9/02/2011
Report examined by :		Date	
			Version: 29 April 2011

				Bridge							Highway	:	BCI(Av):	p.
		NZ TRANSPOF WAKA KOTAHI	RT AGENCY	Kuku	Stre	eam Brie	dge				1			1/2
Brid	lge T	уре:	RC slab,	monoli	thic a	abutment	s							
	ent coo		Severity of			BSN:			9894		Map Ref:			
	No def		1 = as new		D	eck width:			9.30m/		Owner:			
	Not > 5 Moder	ate; 5 - 20%	2 = early s defect	signs of		pan:		of			Last Insp. d	ate:	22/01	/2009
		20 - 50%	3 = moder	rate defec	+	pans:	2/5				Last insp. by: Report Type		GB	/2000
E = :	> 50%		4 = severe			•								
			5 = eleme			otal bridge	_	1:	10.40m		(G1/G2/D/S): G2			
		nt; Sev = Seve				ector: G					Next			
		Structural; R=I	Routine		Date	: 9/02/20)11	ſ			Inspectio	n:		
	Eleme				Ext	Sev	S/R		Brief desci	ription o	of fault and	l co	mments	
Set	No	Descriptio	on				2			-				
	1	Primary elem	ent		С	3	S		ngitudinal crack					
ē	0	-	ransverse be					Cracking	up to 0.35mm v	vide to edg	ges of deck e	xtenc	is into sottit (of slad.
ctu ts	2 3		Tansverse be Other	callis		┤───┨								
Superstructure Elements	3	Half joints				├────┃								
perstructu Elements	4 5	Seismic linka	nes	<u> </u>		├────┃								
Щ			-					Transve	rse cracking up	to 0.3mm	wide to soffit	of ke	rb/footnath	
ຈັ	6	Parapet beam	n or cantileve	er	С	3	S	cantilev						
	7	Cross bracing	9											
	8	Foundations			А	1								
ng	9	Abutments			А	1								
ett.	10	Head wall												
Load-bearing Substructure	11	Pier / column			А	1								
adi	12	Cross-head /	capping bea	ım										
Suc	13	Bearings												
	14	Bearing plinth	n / shelf											
	15	Superstructur	re drainage		А	1								
<u>> s</u>	16	Substructure	<u> </u>		А	1								
ent	17	Movement / e		nts										
	18	Painting: Sup	erstructure											
Durability Elements	19	elements Painting: subs	structura ala	monte				-						
	20	Painting: barr			В	2	R	Minor co	prrosion to handr	rails in nIar	202			
	21	Access / walk	<u> </u>		A	1								
ts /		Guardrail / ha				t	-							
Safety lements	22	fences			С	3	R	Old stee	el handrails on br	ridge, no g	uardrails			
	23	Carriageway			А	1								
Ш	24	Footway / ver	rge / footbrid	ge	А	1								
	25	surfacing Invert / river b	hed		A	1								
> ~	25	Aprons		──┣	17									
Waterway Elements	27	Aggradation			С	3	S	Large a soffit he	mount of gravel	deposited	in span B/C a	igain	st pier B alm	ost at
ate em	28	Degradation		──┣	А	1		Some ne	'Y'''					
ŠΞ	29	Scour			A	1								
	30	River banks		lt	A	1								
g s	31	Revetment / b	batter slope	paving										
Retaining Elements	32	Wing walls			С	2	S	Vertical	cracking up to 0	.2mm wide	e to RHS wing	gwall	at abutment	А
em	33	Retaining wal	lls		А	1			- · ·					
щ	34	Embankment			А	1								
	35	Approach rail		walls	С	3	R	No appr	oach guardrailin	g and old :	steel handrail	s on	bridge	
	36	Signs			С	3	R		smudged/scrate	-			-	
Jer	37	Lighting							U		ĭ			
Other	38	Services			А	1								
	39	Graffiti			А	1								

	Bridge Name:	Highway:	BCI(Av):	р.	
NZ TRANSPORT AGENCY WAKA KOTAHI	Kuku Stream Bridge	1		2/2	

		Comments and Recommendations for Maintenance/Repairs		
Item No.	Element No.	Suggested Remedial Work	Priority (H/M/L)	Estimated Cost
1	36	Replace BSN signs	L	\$ 200
2	35	Install approach guardrailing to all 4 corners and along bridge	L	\$40,000
3	27	Clear out gravel from span B/C	L	\$5,000
4	6	Epoxy inject cracks 0.2mm and wider	L	\$2,000
5	1	Epoxy inject cracks 0.2mm and wider	М	\$5,000
6				
7				
8				
9				
10				
		Total Constru	uction Cost	\$52,200

Remedial work recommended in last inspection has been completed: No

No

(comment below if NO)

NZTA Database changes required:

(Describe change below if answer is YES)

Comments & Recommendations Relating to Future Management (Transfer to current report)

Signs not done, guardrailing not installed, gravel not cleared.

Inspection by:GRG - Bloxam Burnett & Olliver LimitedDate9/02/2011Report examined by:DateDate

Version: 29 April 2011

Bridge Type: RC T-beam, monolithic abuts. Exert code Severity code A = No defect 1 = a sincer 2 = early signs of BSN: 9915 Map Ref: Deck witht: ////////////////////////////////////	4		NZ TRANSPOF WAKA KOTAHI	RT AGENCY	Bridg e Waika		ne: Bridge					Highway 1	/:	BCI(Av):	р. 1/2	
Extent code A = No defect B = Not > 5% Severity code 2 = adfy signs of 3 = moderate defect 5 = sowe defect 3 = moderate defect 5 = sowe defect 5 = sowe defect 5 = element failed BSN: 9915 Map Ref: Deck width: // 8.00m Owner: Ext = Extent : Sev = 56% 3 = moderate defect 5 = element failed 3 = moderate defect 5 = element failed 36.40m Report Type (G1(62/DS)): C Ext = Extent : Sev = Severity Inspector: GRG Next Next Next Marth: S-STuctural: R-Poutine Ext Severity Inspector: GRG Next Sot No Description Ext Sev S/R Brief description of fault and commen 2 Soc. element Transverse beams - - - - 3 5 Semitorian of the addition of the span BC at B (200X0000000000000000000000000000000000	Brid	ae T		RC T-be	am, mo	nolith	nic abuts.								1/2	
A = No defect 1 = as new of defect 1 = as new of defect 0 = Avt > 5% 0 = ant > 5%					-					9915		Map Ref [.]				
Box Markan Structure Signs of Last Insp. date: 22 D = Wide; 20: 50% 3 = moderat offect 5 = element failed Spans: 4/9.1 Last Insp. date: 22 Statistics Sepans: 4/9.1 Last Insp. date: 22 Statistics Sepans: 4/9.1 Last Insp. date: 22 Total bridge length: 36.40m Report Type (G1/G2/DS): C C Main: Sectificition Ext Sectificition No Description Sectificition Sectificiticiciciticition Sectificiticicicicitic				1 = as nev	N							•				
D = wide: 20 - 50% 3 = moderate defect 5 = element failed Spans: 4/9.1 Last Insp. by: 36.40m G Report Type (G1G205): G C Ext = Extent : Sev = Severity Maint : S-Structural; R-Routne Inspector: GRG Next Inspection:					signs of				-4	/0.0011				22/00	22/09/2009	
E = > 50% 4 = severe defect 5 = element failed 1 + 79.1 C = 100 (162,05): (162,02,05): G = 100 (162,05): (162,02,05): G = 100 (162,05): G = 100 (162,05): <thg< td=""><td></td><td></td><td>,</td><td></td><td>rate defec</td><td>•</td><td>•</td><td colspan="2" rowspan="2">4/9.1</td><td></td><td colspan="2">· ·</td><td></td><td>/2009</td></thg<>			,		rate defec	•	•	4/9.1			· ·			/2009		
B Exercise Column and b Total and b <thtotal and="" b<="" th=""> <thtotal and="" b<="" th=""> <thtotal an<="" td=""><td></td><td>,</td><td></td><td></td><td></td><td>S</td><td>pans:</td><td></td><td></td><td></td><td></td><td></td></thtotal></thtotal></thtotal>		,				S	pans:									
Ext = Extent: Sev = Severity Inspector: GRG Next Inspection: Set No Description Ext Sev S/R Brief description of fault and commen Set No Description Ext Sev S/R Brief description of fault and commen Set No Description Ext Sev S/R Vertical cracking to beams up to 0.5m wide, spall at B6 spation of fault and commen 1 Primary element C 3 S Several small spalls to soffit of LHS deck overhang 2 Sec. element Transverse beams - - 1000x300x50mm). 5 Seismic linkages - - 100x300x50mm). - 5 Seismic linkages - - - - 6 Parapet beam or cantilever C 3 S Several small spalls to soffit of LHS deck overhang 7 Cross bracing A 1 - - 10 Head wall - - - - 11 <				5 = eleme	nt failed	T	otal bridge	elength	ı:	36.40n	n			G2		
Maint.: S-Structural; R-Routine Date: 9/02/2011 Inspection: Set No Description Ext Sev S/R Brief description of fault and comment Set No Description Ext Sev S/R Vertical cracking to beams up to 0.3mm wide, spall at B6 spalls 1 Primary element C 3 S Vertical cracking to beams up to 0.3mm wide, spall at B6 spalls 2 Sec. ele- 3 Tansverse beams A 1 A 2 Sec. ele- 3 Tansverse beams A 1 A 4 Haf joints A 1 A A 5 Seleme inhages A A A A 6 Parapet beam or cantilever C 3 S Several small spalls to soffit of LHS deck overhang 7 Cross bracing A 1 A A A A 10 Head wall A 1 A A A A 11 Per / column A 1 A A A A A	Fyt-	- Evto	nt · Sev - Sev	erity		Insp	ector: G	BG	BG				<i>.</i>			
Element Ko Description Ext Sev S/R Brief description of fault and commend (small inpact?), spall to B4 span B/C at B (200x200x50mm), (small inpact?), spall to B4 span B/C at B (200x20x50mm), (small inpact.) 0 <td></td> <td></td> <td>-</td> <td>•</td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> <td>on:</td> <td></td> <td></td>			-	•									on:			
Set No Description Ext Sev S/H Brief description of tault and comment (small impact), spall to B4 span BC at B (20x2050mm), layer of concrete spalled off from soffit of B1 span C/D near (1000x300x50mm). 1 Primary element C 3 S Vertical cracking to beams up to 0.3mm wide, spall at B6 span C/D near (1000x300x50mm). 2 Sec. ele- Transverse beams - - - 4 Half joints - - - - 5 Selsmic linkages - - - - 6 Parapet beam or cantilever C 3 S Several small spalls to soffit of LHS deck overhang 7 Cross breacing A 1 - - 10 Hearing plinh / shelf A 1 - - 11 Fire / column A 1 - - 12 Cross-head / capping beam - - - - 13 Bearing plinh / shelf A 1 - - 14 Bearing plinh /				rioutino					I							
Bit Primary element C 3 S Vertical cracking to beam up to 0.3mm wide, spall at B6 span C/D near to (1000/300/50mm), spart of car B (200x050mm), spart of concrete spalled off from sofit of B1 span C/D near to (1000/300/50mm). Bit Primary element C 3 S <td></td> <td>-</td> <td></td> <td>n</td> <td></td> <td>Ext</td> <td>Sev</td> <td>S/R</td> <td></td> <td>Brief de</td> <td>escription</td> <td>of fault an</td> <td>d co</td> <td>omments</td> <td></td>		-		n		Ext	Sev	S/R		Brief de	escription	of fault an	d co	omments		
Instruction Primary element C 3 S (small impact?), spalt to 84 span B/C at B (200/200X50mm), (1000X300X50mm). Instruction Transverse beams Instruction	Sel	INU	Descriptio	///					Vertical	cracking to	beams up to () 3mm wide	nall :	at R6 snan R/	0	
6 Parapet beam or cantilever C 3 S Several small spalls to soffit of LHS deck overhang 7 Cross bracing C 2 S Fine vertical cracking to end diaphragms. 9 Abutments A 1 10 Head wall A 1 11 Head wall A 1 12 Cross-head / capping beam A 1 12 Cross-head / capping beam A 1 13 Bearings A 1 14 Bearings A 1 16 Substructure drainage A 1 </td <td>ture s</td> <td>1</td> <td>Primary elem</td> <td>ent</td> <td></td> <td>С</td> <td>3</td> <td>S</td> <td>(small i layer of</td> <td>mpact?), spa concrete sp</td> <td>ll to B4 span</td> <td>B/C at B (200</td> <td>x200</td> <td>x50mm), and</td> <td></td>	ture s	1	Primary elem	ent		С	3	S	(small i layer of	mpact?), spa concrete sp	ll to B4 span	B/C at B (200	x200	x50mm), and		
6 Parapet beam or cantilever C 3 S Several small spalls to soffit of LHS deck overhang 7 Cross bracing C 2 S Fine vertical cracking to end diaphragms. 9 Abutments A 1 10 Head wall A 1 11 Head wall A 1 12 Cross-head / capping beam A 1 12 Cross-head / capping beam A 1 13 Bearing plinth / shelf A 1 14 Bearing plinth / shelf A 1 16 Substructure drainage A 1 17 Morement / expansion joints A 1 20 Painting: Substructure elements 21 Access / walkways / gantries A 1 <	ruc		000.0.0	ransverse b	eams											
6 Parapet beam or cantilever C 3 S Several small spalls to soffit of LHS deck overhang 7 Cross bracing C 2 S Fine vertical cracking to end diaphragms. 9 Abutments A 1 10 Head wall A 1 11 Head wall A 1 12 Cross-head / capping beam A 1 12 Cross-head / capping beam A 1 13 Bearings A 1 14 Bearings A 1 16 Substructure drainage A 1 </td <td>rst</td> <td>-</td> <td>()</td> <td>Other</td> <td></td> <td>Α</td> <td>1</td> <td></td> <td> </td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td>	rst	-	()	Other		Α	1									
6 Parapet beam or cantilever C 3 S Several small spalls to soffit of LHS deck overhang 7 Cross bracing C 2 S Fine vertical cracking to end diaphragms. 9 Abutments A 1 10 Head wall A 1 11 Head wall A 1 12 Cross-head / capping beam A 1 12 Cross-head / capping beam A 1 13 Bearing plinth / shelf A 1 14 Bearing plinth / shelf A 1 16 Substructure drainage A 1 17 Morement / expansion joints A 1 20 Painting: Substructure elements 21 Access / walkways / gantries A 1 <	ре Е	-	,													
7 Cross bracing C 2 S Fine vertical cracking to end diaphragms. 8 Foundations A 1 A 1 A 9 Abutments A 1 A A A 10 Head wall A 1 A A A 11 Pier / column A 1 A A A 11 Pier / column A 1 A A A 12 Cross-head / capping beam A 1 A A A 14 Bearings A 1 A A A A 15 Superstructure drainage A 1 A A A A 16 Substructure elements A	Su	-		0					l							
8 Foundations A 1 9 Abutments A 1 10 Head wall A 1 11 Pier / column A 1 12 Cross-head / capping beam A 1 12 Cross-head / capping beam A 1 13 Bearings A 1 A 14 Bearing plinth / shelf A 1 A 16 Superstructure drainage A 1 A 16 Superstructure drainage A 1 A 18 Painting: Superstructure elements A 1 A 20 Painting: substructure elements A 1 A 21 Recess walkways / gartries A 1 22 Guardrail / handrail / safety A 1 A 23 Carriageway surfacing C 3 R Minor areas of seal breaking up on bridge and at approaches 24 Forway / verge / footbridge A 1 A 1 A A 1 <td></td> <td></td> <td></td> <td></td> <td>ər</td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> <td>ang</td> <td></td> <td></td>					ər								ang			
9 Abutments A 1 10 Head wall - - 11 Pier / column A 1 - 11 Pier / column A 1 - 11 Pier / column A 1 - 11 Bearings A 1 - 13 Bearing plinth / shelf A 1 - 14 Bearinge A 1 - - 15 Superstructure drainage A 1 - - 15 Superstructure drainage A 1 - - 16 Painting: Superstructure elements - - - - 18 Painting: substructure elements - - - - - 20 Painting: substructure of a ange A 1 - - - - - - - - - - - - - - -				g				S	Fine ve	rtical crackin	g to end diapl	hragms.				
14 Bearing plinth / shelf A 1 15 Superstructure drainage A 1 16 Substructure drainage A 1 17 Movement / expansion joints A 1 18 Painting: Superstructure elements A 1 19 Painting: Substructure elements A 1 20 Painting: barriers/guardrails A 1 21 Access / walkways / gantries A 1 22 Guardrail / handrail / safety fences A 1 23 Carriageway surfacing C 3 R 24 Footway / verge / footbridge surfacing A 1 25 Invert / river bed A 1 26 Aprons A 1 27 Aggradation A 1 28 Degradation A 1 29 Scour C 3 S Large amount of trees and debris caught on pier D (see phot 30 River banks A 1 31 Revertment / batter slope paving A 1 32 Wing walls C 3 R 33 Retaining walls A 1 <td>50</td> <td>-</td> <td></td>	50	-														
14 Bearing plinth / shelf A 1 15 Superstructure drainage A 1 16 Substructure drainage A 1 17 Movement / expansion joints A 1 18 Painting: Superstructure drainage A 1 17 Movement / expansion joints A 1 18 Painting: Superstructure elements A 1 19 Painting: barriers/guardrails A 1 20 Painting: barriers/guardrails A 1 21 Access / walkways / gantries A 1 22 Guardrail / handrail / safety fences A 1 23 Carriageway surfacing C 3 R 23 Carriageway surfacing C 3 R 24 Footway / verge / footbridge surfacing A 1 25 Invert / river bed A 1 26 Aprons A 1 25 Rogradation A 1 29 Scourt C 3 S Large amount of trees and debris caught on pier D (see phot 30 River banks A 1 31 Revetment / batter slope pavin	rinç					A	1									
14 Bearing plinth / shelf A 1 15 Superstructure drainage A 1 16 Substructure drainage A 1 17 Movement / expansion joints A 1 18 Painting: Superstructure drainage A 1 17 Movement / expansion joints A 1 18 Painting: Superstructure elements A 1 19 Painting: barriers/guardrails A 1 20 Painting: barriers/guardrails A 1 21 Access / walkways / gantries A 1 22 Guardrail / handrail / safety fences A 1 23 Carriageway surfacing C 3 R 24 Footway / verge / footbridge surfacing A 1 25 Invert / river bed A 1 26 Aprons A 1 27 Aggradation A 1 28 Degradation A 1 29 Scour C 3 S Large amount of trees and debris caught on pier D (see phot 30 River banks A 1 31 Revetment / batter slope paving A	eal uct															
14 Bearing plinth / shelf A 1 15 Superstructure drainage A 1 16 Substructure drainage A 1 17 Movement / expansion joints A 1 18 Painting: Superstructure drainage A 1 17 Movement / expansion joints A 1 18 Painting: Superstructure elements A 1 19 Painting: barriers/guardrails A 1 20 Painting: barriers/guardrails A 1 21 Access / walkways / gantries A 1 22 Guardrail / handrail / safety fences A 1 23 Carriageway surfacing C 3 R 24 Footway / verge / footbridge surfacing A 1 25 Invert / river bed A 1 26 Aprons A 1 27 Aggradation A 1 28 Degradation A 1 29 Scour C 3 S Large amount of trees and debris caught on pier D (see phot 30 River banks A 1 31 Revetment / batter slope paving A	d-b str					A	1									
14 Bearing plinth / shelf A 1 15 Superstructure drainage A 1 16 Substructure drainage A 1 17 Movement / expansion joints A 1 18 Painting: Superstructure elements A 1 19 Painting: Substructure elements A 1 20 Painting: barriers/guardrails A 1 21 Access / walkways / gantries A 1 22 Guardrail / handrail / safety fences A 1 23 Carriageway surfacing C 3 R 24 Footway / verge / footbridge surfacing A 1 25 Invert / river bed A 1 26 Aprons A 1 27 Aggradation A 1 28 Degradation A 1 29 Scour C 3 S Large amount of trees and debris caught on pier D (see phot 30 River banks A 1 31 Revertment / batter slope paving A 1 32 Wing walls C 3 R 33 Retaining walls A 1 <td>oac</td> <td></td> <td colspan="3"></td> <td>•</td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td>	oac					•										
15 Superstructure drainage A 1 16 Substructure drainage A 1 17 Movement / expansion joints A 1 18 Painting: Superstructure elements A 1 19 Painting: bariers/guardrails A 1 20 Painting: bariers/guardrails A 1 21 Access / walkways / gartries A 1 22 Guardrail / handrail / safety fences A 1 23 Carriageway surfacing C 3 R Minor areas of seal breaking up on bridge and at approaches 24 Footway / verge / footbridge surfacing A 1 A A 25 Invert / river bed A 1 A A A 25 Invert / river bed A 1 A	νĽ		BearingsBearing plinth / shelf													
16 Substructure drainage A 1 17 Movement / expansion joints A 1 18 Painting: Superstructure elements - - 20 Painting: substructure elements - - 20 Painting: substructure elements - - 21 Access / walkways / gantries - - 22 Guardrail / handrail / safety fences A 1 - 23 Carriageway surfacing C 3 R Minor areas of seal breaking up on bridge and at approaches 24 Footway / verge / footbridge surfacing A 1 - 25 Invert / river bed A 1 - 26 Aprons - - - 27 Aggradation A 1 - 28 Degradation A 1 - 29 Scour C 3 S Large amount of trees and debris caught on pier D (see phot 30 River banks A 1 - - - 33 Retaining walls																
17 Movement / expansion joints A 1 18 Painting: Superstructure elements A 1 19 Painting: substructure elements A 1 20 Painting: substructure elements A 1 21 Access / walkways / gantries A 1 22 Guardrail / handrail / safety fences A 1 23 Carriageway surfacing C 3 R Minor areas of seal breaking up on bridge and at approaches 24 Footbway / verge / footbridge surfacing A 1 A 1 25 Invert / river bed A 1 A 1 26 Aprons A 1 A 1 26 Aprons A 1 A 1 27 Aggradation A 1 A 1 28 Degradation A 1 A 1 29 Scour C 3 S Large amount of trees and debris caught on pier D (see phot 30 Retaining walls A 1 31 Revetment / batter s				× ×												
19 Painting: substructure elements A 1 20 Painting: barriers/guardrails A 1 21 Access / walkways / gantries - - 22 Guardrail / handrail / safety fences A 1 23 Carriageway surfacing C 3 R Minor areas of seal breaking up on bridge and at approaches 24 Footway / verge / footbridge surfacing A 1 - 25 Invert / river bed A 1 - 26 Aprons - - - 27 Aggradation A 1 - 28 Degradation A 1 - 29 Scour C 3 S Large amount of trees and debris caught on pier D (see phot 30 River banks A 1 - - 31 Revetment / batter slope paving A 1 - 32 Wing walls C 3 R Erosion hole formed behind abutment E RHS wingwall (see point) 34 Embankments A 1 -	lity			Ŷ	nte											
19 Painting: substructure elements A 1 20 Painting: barriers/guardrails A 1 21 Access / walkways / gantries - - 22 Guardrail / handrail / safety fences A 1 23 Carriageway surfacing C 3 R Minor areas of seal breaking up on bridge and at approaches 24 Footway / verge / footbridge surfacing A 1 - 25 Invert / river bed A 1 - 26 Aprons - - - 27 Aggradation A 1 - 28 Degradation A 1 - 29 Scour C 3 S Large amount of trees and debris caught on pier D (see phot 30 River banks A 1 - - 31 Revetment / batter slope paving A 1 - 32 Wing walls C 3 R Erosion hole formed behind abutment E RHS wingwall (see point) 34 Embankments A 1 -	abi				111.5	Α										
19 Painting: substructure elements A 1 20 Painting: barriers/guardrails A 1 21 Access / walkways / gantries - - 22 Guardrail / handrail / safety fences A 1 23 Carriageway surfacing C 3 R Minor areas of seal breaking up on bridge and at approaches 24 Footway / verge / footbridge surfacing A 1 - 25 Invert / river bed A 1 - 26 Aprons - - - 27 Aggradation A 1 - 28 Degradation A 1 - 29 Scour C 3 S Large amount of trees and debris caught on pier D (see phot 30 River banks A 1 - - 31 Revetment / batter slope paving A 1 - 32 Wing walls C 3 R Erosion hole formed behind abutment E RHS wingwall (see point) 34 Embankments A 1 -	ura iler	18														
21 Access / walkways / gantries		19	Painting: sub	structure ele	ments											
And Sector A 1 22 Guardrail / handrail / safety fences A 1 23 Carriageway surfacing C 3 R Minor areas of seal breaking up on bridge and at approaches surfacing 24 Footway / verge / footbridge surfacing A 1 Image: Seal breaking up on bridge and at approaches 24 Footway / verge / footbridge surfacing A 1 Image: Seal breaking up on bridge and at approaches 24 Footway / verge / footbridge surfacing A 1 Image: Seal breaking up on bridge and at approaches 25 Invert / river bed A 1 Image: Seal breaking up on bridge and at approaches 26 Aprons Image: Seal breaking up on bridge and at approaches A 1 26 Aprons Image: Seal breaking up on bridge and at approaches A 1 27 Aggradation A 1 Image: Seal breaking up on bridge and at approaches 27 Aggradation A 1 Image: Seal breaking up on bridge and at approaches 29 Scour C 3 S Large amount of trees and debris caught on pier D (see phot 30 Riv		20	Painting: barr	riers/guardra	ils	Α	1									
Yes 23 Carriageway surfacing C 3 R Minor areas of seal breaking up on bridge and at approaches 24 Footway / verge / footbridge surfacing A 1		21														
Yes 23 Carriageway surfacing C 3 R Minor areas of seal breaking up on bridge and at approaches 24 Footway / verge / footbridge surfacing A 1 Image: Seal breaking up on bridge and at approaches 25 Invert / river bed A 1 Image: Seal breaking up on bridge and at approaches 26 Aprons A 1 Image: Seal breaking up on bridge and at approaches 27 Aggradation A 1 Image: Seal breaking up on bridge and at approaches 27 Aggradation A 1 Image: Seal breaking up on bridge and at approaches 28 Degradation A 1 Image: Seal breaking up on bridge and at approaches 30 River banks A 1 Image: Seal breaking up on bridge and at approaches 30 River banks A 1 Image: Seal breaking up on bridge and at approaches 31 Revetment / batter slope paving A 1 Image: Seal breaking up on bridge and at approaches 32 Wing walls C 3 R Erosion hole formed behind abutment E RHS wingwall (see particle breaking up on bridge and the particle breaking up on bridge and the particle breaking up on bridge an	nts	22		andrail / safe	ty	А	1									
24 surfacing A 1 25 Invert / river bed A 1 26 Aprons - - 27 Aggradation A 1 28 Degradation A 1 29 Scour C 3 S 30 River banks A 1 31 Revetment / batter slope paving A 1 32 Wing walls C 3 R 33 Retaining walls - - 34 Embankments A 1 35 Approach rails / barriers / walls A 1 36 Signs A 1	afe me			surfacing	┣			D	Minora	reas of cool	broaking up a	n bridge and	at on	proachoc		
24 surfacing A 1 25 Invert / river bed A 1 26 Aprons - - 27 Aggradation A 1 28 Degradation A 1 29 Scour C 3 S 30 River banks A 1 31 Revetment / batter slope paving A 1 32 Wing walls C 3 R 33 Retaining walls - - 34 Embankments A 1 35 Approach rails / barriers / walls A 1 36 Signs A 1	Ele S				de			11		1000 UI SEAI	oreaning up 0	n bhuye anu	ai ap	pidaciies.		
26 Aprons Image: Market and the state a		24			30	A	1									
30 River banks A 1 31 Revetment / batter slope paving A 1 32 Wing walls C 3 R 33 Retaining walls A 1 34 Embankments A 1 35 Approach rails / barriers / walls A 1 36 Signs A 1		25		bed		А	1									
30 River banks A 1 31 Revetment / batter slope paving A 1 32 Wing walls C 3 R 33 Retaining walls A 1 34 Embankments A 1 35 Approach rails / barriers / walls A 1 36 Signs A 1	/ay its															
30 River banks A 1 31 Revetment / batter slope paving A 1 32 Wing walls C 3 R 33 Retaining walls A 1 34 Embankments A 1 35 Approach rails / barriers / walls A 1 36 Signs A 1	erv ner								I							
30 River banks A 1 31 Revetment / batter slope paving A 1 32 Wing walls C 3 R 33 Retaining walls A 1 34 Embankments A 1 35 Approach rails / barriers / walls A 1 36 Signs A 1	/ati len								<u> </u>							
State 31 Revetment / batter slope paving A 1 32 Wing walls C 3 R Erosion hole formed behind abutment E RHS wingwall (see paving walls) 33 Retaining walls A 1 A 34 Embankments A 1 A 35 Approach rails / barriers / walls A 1 A 36 Signs A 1 A	< ш				┣			S	Large a	mount of tre	es and debris	caught on pie	er D (see photo).		
35 Approach rails / barriers / walls A 1 36 Signs A 1				hottor alara -	novina											
35 Approach rails / barriers / walls A 1 36 Signs A 1	inç nts			Datter Slope	paving			P	Freeir	holo forma	bobind shut		din en c	all (and the st		
35 Approach rails / barriers / walls A 1 36 Signs A 1	ain me			 0		U	3	К	Erosion	noie formed	i benina abuth		virigw	aii (see photo	ונ	
35 Approach rails / barriers / walls A 1 36 Signs A 1	Ret					•										
36 Signs A 1	<u>a</u> m				wells											
30 Signs A I 37 Lighting				is / barriers /	walls											
Š 3/ Lignung	۲.		-			А										
	the					٨	1									
	0															
39 Graffiti A 1		39	Graniti		<u> </u> -	А										

Bridge Name:	Highway:	BCI(Av):	р.
Waikawa Bridge	1		2/2

		Comments and Recommendations for Maintenance/Repairs		
Item No.	Element No.	Suggested Remedial Work	Priority (H/M/L)	Estimated Cost
1	1	Epoxy inject all cracks 0.2mm and wider	М	\$20,000
2	1	Repair spalls	М	\$5,000
3	23	Reseal/repair potholes etc	М	\$2,000
4	29	Cut up and remove debris from pier D	Н	\$2,000
5	33	Fill hole behind abutment E RHS wingwall	М	\$ 500
6	6	Repair spalls	L	\$5,000
7				
8				
9				
10				
		Total Constru	uction Cost	\$34,500

Remedial work recommended in last inspection has been completed: No (comment below if NO)

NZTA Database changes required: No

(Describe change below if answer is YES)

Comments & Recommendations Relating to Future Management (Transfer to current report)

Spalls not repaired.

Inspection by :	GRG - Bloxam Burnett & Olliver Limited	Date 9/02/2011	
Report examined by :		Date	

Version: 29 April 2011

				Bridg	e Nar	ne:					Highway	:	BCI(Av):	-	
		NZ TRANSPOR WAKA KOTAHI	RT AGENCY	Mana	akau	North F	Rail C	Overbri	dge		1			р. 1/2	
Brid	lge T	vne:	RC T-be	am mo	nolith	ic abuts									
	ent co		Severity			BSN:			9919		Map Ref:				
	No def		1 = as nev	w	D	eck width:			7.50m/		Owner:				
	Not > { Moder	5% ate; 5 - 20%	2 = early s defect	signs of		pan:	•	of	7.5011/		Last Insp. o	lato.	22/01	/2000	
		20 - 50%	3 = mode	rate defe		pan: pans:	0	-	2/9.1, 3/12.2)			GB	2003	
	> 50%		4 = severe								Last insp. I Report Typ	-			
			5 = eleme	ent failed		otal bridge	-	1:	91.50m		(G1/G2/D/S): G2				
		nt; Sev = Sev		_		ector: C					Next				
		Structural; R=	Routine		Date	: 10/02/2	2011	Π			Inspectio	on:			
	Eleme				Ext	Sev	S/R		Brief desc	ription o	of fault and	d co	mments		
Set	No	Descriptio	on				•/	R Brief description of fault and comments Fine vertical cracking up to 0.1mm wide to beams, and severe s							
	1	Primary elem	ent		D	4	S		tical cracking u ee schedule).	p to 0.1mm	n wide to bear	ns, a	nd severe sp	alling to	
, nre	2	Sec. ele- T	ransverse b	eams					,						
uct	3	ment(s) C	Other		С	2	S	Fine dec	k soffit crackin	g both way	s up to 0.2mr	n wid	е		
perstructu Elements	4	Half joints													
Superstructure Elements	5	Seismic linka	ges												
	6	Parapet beam	n or cantilev	er	С	3	S		rse cracking up several (see s		wide to soffit	of de	ck overhang	and	
	7	Cross bracing	g		А	1									
	8	Foundations			А	1									
ing	9	Abutments			А	1									
sari	10	Head wall													
št P	11	Pier / column			D	3	S		to many colum		,				
Load-bearing Substructure	12	Cross-head /	capping bea	am	С	3	S	Spalling	to crossheads	at pier E a	nd G (see sch	nedul	e)		
ЧŇ	13	Bearings	/ 1 16												
	14 15	Bearing plinth			٨	1									
	16	Superstructure Substructure			A A	1									
lity nts	17	Movement / e	<u> </u>	ints	B	2	S	Minor re	flective crackin	a over abu	tment Lioint				
Durability Elements	18	Painting: Sup					-			9					
		elements													
	19	Painting: sub													
	20 21	Painting: barr	ÿ		A	1									
S.		Access / walk Guardrail / ha						Guardra	il on LHS only	concrete h	andrail on RH	S an	d no cycle ra	il flare	
Safety lements	22	fences		·· <i>y</i>	С	3	R	downs o				J, al	a no oyole la	ii iiule	
Saf	23	Carriageway	-		Α	1									
Ξ	24	Footway / ver surfacing	rge / footbrid	lge	А	1									
	25	Invert / river b	oed												
ay	26	Aprons													
Waterway Elements	27	Aggradation													
ate	28	Degradation													
≥≣	29	Scour													
D "	30	River banks	hottor alara -	pov/r c	^										
ing	31 32	Revetment / I	Datter stope	paving	A A	1									
ain	32	Wing walls Retaining wal	lle		А	1									
Retaining Elements	33	Embankment			А	1									
				wolle			D	Texas tv	vist terminals a	t 3 corners	and damage	to ~1	0m of rail at		
	35	Approach rail	is / parriers /	walls	D	3	R	abutmer							
er	36	Signs			A	1									
Other	37	Lighting													
	38 39	Services			A B	1 2	R	Minor gr	affiti						
	39	Graffiti			D	۷	n	winter gr	ann						
								1							

Comments and Recommendations for Maintenance/Repairs								
Item No.	Element No.	Suggested Remedial Work	Priority (H/M/L)	Estimated Cost				
1	35	Install complying terminals at 3 corners	М	\$30,000				
2	35	Replace 10m of guardrail	L	\$2,000				
3	22	Install guardrail along RHS	М	\$20,000				
4	12	Repair spalls	М	\$1,000				
5	11	Repair spalls	Н	\$30,000				
6	6	Repair spalls	L	\$1,200				
7	6	Epoxy inject cracks 0.2mm and wider	L	\$20,000				
8	1	Repair spalls	Н	\$35,000				
9	22	Install 2 cycle flare downs	L	\$1,000				
10								
Total Construction Cost				\$140,200				

NZTA Database changes required:	Yes	(Describe change below if answer is YES)
Guardrail amended		
Comments & Recommendations Relations	ating to Future Ma	nagement (Transfer to current report)
Guardrail not done, spalls not repaired.		

Inspection by :	GRG - Bloxam Burnett & Olliver Limited	Date	10/02/2011
Report examined by :		Date	