
Appendix A





Summary Engineering Geology Along the Route


Project: Transmission Gully


As Shown


Notice of Requirement and Consents Scale: Figure: Date:


Project No: November 2011 5C1591.00


Α























NZ TRANSPORT AGENCY WAKA KOTAHI

Prepared for:



Title: Resilience of Road Network in the Wellington Region - Availability State

Project: Transmission Gully

Notice of Requirement and Consents

Date: Project No: Figure:

As Shown November 2011 5

5C1591.00

Figure E - Resilience and Availability and Outage States




Illustration 1 - Resilience of Network Time

Resilience States

Table E-1 Availability State

rable E I Availability Sta		Diate
Availability Level	Availability State	Availability Description
1	Full	Full access except condition may require care.
2	Poor	Available for slow access, but with difficulty by normal vehicles due to partial lane blockage, erosion or deformation.
3	Single Lane	Single lane access only with difficulty due to poor condition of remaining road; possible weight restriction on bridges.
4	Difficult	Single lane accessible by only 4x4 off road vehicles, or severe weight restriction on bridges, with access for special vehicles only.
5	Closed	Road closed and unavailable for use.

Table E-2 Outage State

Prepared by:

Outage Level	Outage State	Duration of Availability Condition
1	Open	No closure, except for maintenance
2	Minor	Condition persists for up to 3 days
3	Moderate	Condition persists for 3 days to 2 weeks
4	Severe	Condition persists for 2 weeks to 3 months
5	Long term	Condition persists for > 3 months

Prepared for:

NZ TRANSPORT AGENCY



Title: Resilience and Availability and Outage States

Project: Transmission Gully

Notice of Requirement and Consents

 Scale:
 Date:
 Project No:

 N.T.S
 November 2011
 5C1591.00

Figure:



FAILURE OF ROAD DUE TO LIQUEFACTION AND LATERAL SPREADING IN THE 2011 CHRISTCHURCH EARTHQUAKE



FAILURE OF ROAD EMBANKMENTS DUE TO LIQUEFACTION IN THE 1931 HAWKES BAY EARTHQUAKE

Prepared by:





Title: Damage to Roads From Liquefaction and Lateral Spreading

Project: Transmission Gully
Notice of Requirement and Consents

Scale: Date: N.T.S November 2011

Project No: 5C1591.00 Figure:

F



FAULT RUPTURE ACROSS EMBANKMENT, ACCESS RESTORED WITHIN DAYS AFTER THE 2008 WENCHUAN EARTHQUAKE, CHINA



FAULT RUPTURE CAUSING BRIDGE COLLAPSE, ACCESS NOT RESTORED 6 MONTHS AFTER THE 2008 WENCHUAN EARTHQUAKE, CHINA

Prepared by:






Title: Fault Rupture Effects and Recovery After 2008 Wenchaun Earthquake

Project: Transmission Gully

Notice of Requirement and Consents

Scale: Date: N.T.S November 2011

Project No: Figure: 5C1591.00





Prepared by:




Title: Reinforced Soil Embankments

Project: Transmission Gully
Notice of Requirement and Consents

Scale:	Date:
NTS	Newsember 201

Project No: 5C1591.00 Figure: H







Prepared by:

Title: Rock Slope Configuration and Rock Fall Protection

Project: Transmission Gully

Notice of Requirement and Consents

Scale: Project No: Figure:

N.T.S November 2011

5C1591.00

I I

