# MINO-456 Masterton speed review

7 September 2022

Information on the Masterton to Featherston speed review, where Carterton is along the route.

---

**Waka Kotahi NZ Transport Agency's response:**

- There has been a high number of crashes on this section of State Highway 2 from Masterton to Featherston, between January 2010 and December 2019 there were 488 crashes. Four people were killed and 28 people were seriously injured.
- We formally consulted on proposed new speed limits for State Highway 2 between Masterton and Featherston in August and September 2021. This followed earlier rounds of community engagement.
- Carterton sits within the corridor undergoing the speed review, it is not subject to a separate review.
- Our safety team has been considering the feedback received from the consultation.
- We will share a consultation report and the submissions when we announce our decision later in 2022.
- s 9(2)(g)(i) [redacted]

**Note:**

- Waka Kotahi is also currently implementing infrastructure improvements between Masterton and Carterton as part of the Road to Zero Speed and Infrastructure Programme. The improvements compliment the proposed speed limit changes and includes installing three roundabouts, median barrier and related minor safety improvements.
- This is separate from the Masterton to Featherston speed review.

Released under the Official Information Act 1982