From: Chris Harris
To: \$ 9(2)(a)

Subject: Fwd: SH 1-Kilmog remove trees on NZTA LAND-Rapid 2749

Date: Tuesday, 29 September 2020 2:48:54 PM

Attachments: KilmogSH1-Rapid 2749 \$ 9(2) -26th Sept 020.pdf

 $Hi^{s} \frac{9(2)}{(2)}$,

Can you please check to see if the trees around this address are in the hazardous tree register. Might pay to undertake an inspection next time you are passing as well. We are removing trees outside \$9(2)(a), but don't intend on touching these at present.

Thanks

Chris Harris NZTA - Coastal Otago

Sent via mobile

From: \$ 9(2)(a)

Sent: Tuesday, September 29, 2020 12:05:40 PM **To:** Chris Harris < Chris. Harris@nzta.govt.nz>

Subject: SH 1-Kilmog remove trees on NZTA LAND-Rapid 2749

Hi Chris

Hope all is well at NZTA with all this snow.

I had a call from the other day after I saw win relation to suggesting the removal of some of the trees at the entrance of Rapid 2749 ie all on NZTA land. Travel from their entrance out onto SH1 esp heading south requires special attention as vehicle travel fast down off the hill going north.

I said I would raise the matter with you. Refer to photos attached.

It seems a very worthwhile project to remove these trees (about 10-11) on the east side of the stream ie all on NZTA land. In particular if we are felling the 6-7 trees on the property next door ie \$9(2)(a) it would seem a practical and economic operation whilst all the gear is on site.

I will leave that over to you to discuss and resolve.

Owner is 9(2)(a) and partner (her cell phone is 9(2)(a)

Regards \$/9(2)(a)

Land and Forest Consultants Ltd Box 5990 Dunedin 9054

s 9(2)(a) Office 03 476 6251

E. mail .. **S** 9(2)(a)

Web site.. www.landandforestconsultants.co.nz

Kilmog-SH1—Trees on NZTA Land Rapid 2749



Photo 1

View from opposite Russell road corner on SH1

LOOKING north to mainly pine trees in background on a narrow strip on NZTA Land. nto 2



Small group of pine trees with a lean towards SH1 before entrance on the south side to rapid 2749 property.

Very easy to cut down and remove before issues arise.

NZTA land on east side of the stream with a new access track on the left.



Photo 3

with Tall pines and two with large branches now lying out towards SH1. A group of trees on NZTA land on east side of the stream.

Entrance to Drive in on the left can be seen.

The property owner is \$9(2)(a) partner s 9(2)(a)



View of entrance way off SH1 looking south. One tall Eucalyptus tree in the middle, most are pines. A pine tree with a lean towards SH1 can be seen on the left of the Eucalyptus.

Traffic safety will be greatly improved with access onto SH1 if these trees are felled in particular driving out heading south onto SH1.




Photo 5

View directly into entrance to RAPID 2749 with a narrow large culvert over the stream.

Approx a group of 8-10 trees on the left of the entrance would be beneficial in felling. They are all on NZTA land.

Photographs Taken by \$9(2)(a) for NZTA.

Land and Forest Consultants 9(2)(a) DATED ...26⁷⁴ September 2020.