Confirmed state highway projects 2024/27

Crown Resilience Programme

Date: October 2024

The following projects have been funded by the Crown Resilience Programme.

Region	Project	Hazard type	Funding type*	Status
N. d.l.	T. II. D. "D." A.II. "		0 " 1	01 1
Northland	Te Hana Rail Bridge 1 Underslip	Underslip	Small-to- medium	Started
	Whakaniray Dood Hadaralia Ta Hana sita	Lladorolia	Small-to-	Ctartad
	Whakapirau Road Underslip Te Hana site 2 between the two bridges	Underslip	medium	Started
	Schiska Road Underslip	Underslip	Small-to-	Started
	Ochliska Road Oridership	Ondersilp	medium	Started
	Omeru Falls	Underslip	Small-to-	Started
	Omera i and	Cridoronp	medium	Ctartou
	Northland Subsidence Strategy	Underslip	Small-to-	Started
	3,		medium	
	Long Hill slip 2 Lake Rotokereru Underslip	Underslip	LCLR	Started
	2	·		
	Lookout Hill Underslip 1	Underslip	LCLR	Started
	Lookout Hill Underslip 2	Underslip	LCLR	Started
New	Brynderwyns Sediment Control	Underslip	LCLR	Approved
Projects	DV1 - North Slump	Underslip	LCLR	Approved
2024/27	#9 - DV3 Northbound Wall- Underslip	Underslip	LCLR	Approved
	#18 - SH16 Jordan Rd	Underslip	LCLR	Approved
	Te Hana Nurseries Slip	Underslip	LCLR	Approved
	#6 - DV1 South Guardrail Slump	Underslip	LCLR	Approved
	SH12 Opononi Slip Gravity Wall	Overslip	LCLR	Approved
	Hill Street Culvert	Surface	LCLR	Approved
	1 18808 41 1 5 41	Flooding	1.01.5	
	Long Hill Slip 4 Lake Rotokereru Underslip 4	Underslip	LCLR	Approved
	Saunders Road Underslip	Underslip	LCLR	Approved
Auckland	SH1 Hillcrest Creek Flooding	Flooding	LCLR	Completed
, taomana	Green based solutions trial at state	Overslip	Small-to-	Started
	highway slip locations	G 7 G 1 G 1 G	medium	- 13.153
	SH1 Soakage Khyber Pass/Gillies Ave	Flooding	Small-to-	Started
	· ·	ŭ	medium	
	SH18 Offramp Slip Stabilisation	Underslip	LCLR	Started
	SH1 Whangamarino Slip	Overslip	LCLR	Started
	Detour Routes	Detour route	LCLR	Started
		vulnerability		
	SH22 Rapid Flood Hazard Mapping	Flooding	LCLR	Started
New	Tank Farm culvert to Exmouth coastal	Coastal	Small-to-	Approved
Projects 2024/27	resilience	Inundation	medium	Ammanad
	SH1 Penrose to SEART Flooding	Flooding	Small-to-	Approved
	SH22 Paerata Pump Station	Flooding	medium Small-to-	Approved
	Orizz i acrata i unip Station	1 looding	medium	Approved
	SH22 Bycroft West Culvert Capacity	Flooding	Small-to-	Approved
	2 By or one treat survent supports	. 10001119	medium	, ipp10100
	Underslip 002 / 294 / 8.440	Underslip	LCLR	Approved
			,	





Bay of	SH35 Hawai River Bridge	Bridge scour	LCLR	Approved
Plenty	Rock scaling at various locations - Waioeka gorge	Rockfall	LCLR	Approved
	SH29A Maungatapu Bridge	Seismic vulnerability	LCLR	Started
	SH2 Te Mania Stream Bridge	Bridge scour	LCLR	Approved
	Ruahihi Bluff	Rockfall	LCLR	Started
	SH2 Waioeka River Groynes	River erosion	LCLR	Started
	Overslip SH 035 / 079 / 8.92	Overslip	LCLR	Approved
	SH5 Wharepapa Stream Bridge	Bridge scour	LCLR	Started
New Projects 2024/27	Omoko Underslip	River Erosion	LCLR	Approved
	SH2 Tuapiro Stream Bridge	Bridge Scour	LCLR	Approved
	Site#143 Raukokore River East	Underslip	LCLR	Approved
	SH35 Pirikaraka Stream Bridge	Bridge Scour	LCLR	Approved
Waikato	SH3 Te Kuiti Slip (SH3-0076/7.066-7.232)	Overslip	LCLR	Started
	SH31 Puti Bluffs East Coastal Erosion	Coastal erosion	LCLR	Started
	SH41Waihi Hill Hipaua Steaming Cliffs Slip	Underslip	LCLR	Started
	SH23 Raglan Divvy - Drainage (SH23- 0015/5.950-6.060)	Flooding	LCLR	Started
	SH1B Mangatoketoke Stream Bridge	Bridge scour	LCLR	Started
	SH25 Ramarama Stream Bridge	Bridge scour	LCLR	Started
	SH5 Mihi Stream Bridge	Bridge scour	LCLR	Approved
	SH41 R-Waihi Hill 2 Scour (# 33)	River erosion	LCLR	Cancelled
	SH41 R-Waihi Hill Scour (# 32) (60050801)	Underslip	LCLR	Started
New	SH32 Swampy Stream Bridge	Bridge Scour	LCLR	Approved
Projects	SH5 Rangitaiki River Bridge	Bridge Scour	LCLR	Approved
2024/27	SH1 R-Waikato River Bridge Slip (# 02)	River Erosion	LCLR	Approved
	SH1 Bulli Point (Te Poporo) Site 1	Underslip	Small-to- medium	Approved
	SH1 Bulli Point (Te Poporo) Site 2	Underslip	Small-to- medium	Approved
	SH46 Tongariro Culvert upgrade	Flooding	LCLR	Approved
	Paraunui Slumping	Underslip	Small-to- medium	Approved
	SH29 Rapurapu slip 2 (site 119)	Overslip	LCLR	Approved
	Diehard Rock	Rockfall	LCLR	Approved
	Monitoring Site 4 - Whakatete Bay	Overslip	LCLR	Approved
	Monitoring Site 3	Overslip	LCLR	Approved
	SH29 Kaimai Summit rockfall (Site 122)	Rockfall	LCLR	Approved
	Bee Sting Underslip - Coromandel	Underslip	LCLR	Approved
	Mataora Rockface	Rockfall	LCLR	Approved
	Hikuai Hills Erosion	Coastal Erosion	LCLR	Approved
	Kuaotunu Beach Gabion Erosion	Coastal Erosion	LCLR	Approved
	Monitoring Site 6 - Multiple sites	Overslip	Small-to- medium	Approved
	Site 58 Thames Coast Rockfall	Rockfall	LCLR	Approved
	Monitoring Site 2	Overslip	LCLR	Approved
	River Bend Underslip 2	River Erosion	LCLR	Approved
	Monitoring Site 7	Coastal Erosion	LCLR	Approved
	SH27 Patetonga Drain slip (Site159)	Underslip	LCLR	Approved
	Victoria Battery Underslip	Underslip	LCLR	Approved
	Bad Boss Culvert Underslip	Underslip	LCLR	Approved

	D : 0 1 0144 0		1.01.0	
	Dairy Creek CMA Scour	Underslip	LCLR	Approved
	Waikumete Shoulder Slumping (Site #34)	Underslip	LCLR	Approved
	SH2 Karangahake Gorge various	Underslip	LCLR	Approved
	Retaining Wall upgrades			
	Patetonga Embankment (Site 60)	Underslip	LCLR	Approved
	SH26 Komata River Bridge	Bridge Scour	LCLR	Approved
	SH3 Awawino Hill - Mesh Overslip	Underslip	LCLR	Approved
Tairawhiti	R-Waihuka Straight	Flooding	Small-to-	Approved
New			medium	
Projects	State Highway 35 and State Highway 2	Various	Small-to-	Approved
2024/27	resilience works.		medium	
	R-Otoko Hill Descent III	Overslip	LCLR	Approved
	R-Farams Subsidence	Underslip	Small-to-	Approved
		· ·	medium	
	R-Makaratu Road Subsidence	Underslip	LCLR	Approved
Hawkes Bay	SH2 Mohaka Hill	Underslip	LCLR	Approved
New	Waipawa River Erosion	River Erosion	LCLR	Approved
Projects	Bayview Drain Culvert	Flooding	LCLR	Approved
2024/27	Morere Hill Dropout	Underslip	LCLR	Approved
	Mohaka Hill debris fence	Rockfall	LCLR	Approved
	Culvert No.85	Underslip	LCLR	Approved
	Culvert No.85	Underslip	LCLR	Approved
Taranaki	SH4 Waterfall Hill	Underslip	LCLR	Started
Taranaki			LCLR	Started Started
	Rapanui Retaining Wall	Underslip		
	SH3 Mahoenui Hill Retaining Wall	Underslip	LCLR	Cancelled
New	SH45 Rahotu Culvert	Flooding	LCLR	Approved
Projects	SH3 Tongaporutu Scenic Viewpoint	Underslip	LCLR	Approved
2024/27		E	1.01.5	
Manawatū/	SH4 Putiki Culvert	Flooding	LCLR	Started
Whanganui	SH54 Tapuae Road Underslip	Underslip	LCLR	Started
	Site 15-Mangawhero River opp. Raupiu	Overslip	LCLR	Approved
	Site 26-Mangawhero River – Culvert no	Rockfall	LCLR	Started
	73 to passing lane			
New	Site 25-Mangawhero River – end of KCC	Rockfall	LCLR	Approved
Projects	LHS to Culvert No 73	5 17 11	1.01.5	
2024/27	Site 9-Mangawhero River – YMCA Camp	Rockfall	LCLR	Approved
	Site 5-Mangawhero River	Underslip	LCLR	Approved
Wellington	SH1 Tawa to Johnsonville Surface	Various	Small-to-	Approved
	Flooding & Slips pavement failure -		medium	
	corridor study			
	R-SH59 Three Sisters rock face rockfall	Rockfall	LCLR	Started
	R-SH2 Remutaka Hill westbound (several	Rockfall	LCLR	Started
	sites) UAV survey			
	R-SH1 Landslip below 16 Japonica Grove	Overslip	LCLR	Started
	reprofile			
New	R-SH2 Korokoro Stream debris trap	Flooding	LCLR	Approved
Projects	R-SH1 Plimmerton Roundabout flooding	Flooding	LCLR	Approved
=	D. Old Condition of a second of	Overslip	LCLR	Approved
2024/27	R-SH1 Southbound onramp, south of			
=	Westchester Drive Bridge -	·		
=	Westchester Drive Bridge - R-SH2 Rockface between Te Marua &	Rockfall	LCLR	Approved
_	Westchester Drive Bridge - R-SH2 Rockface between Te Marua & Birchville Park	Rockfall		
_	Westchester Drive Bridge - R-SH2 Rockface between Te Marua & Birchville Park R-SH2 Featherston SuperValue Area	·	LCLR LCLR	Approved Approved
2024/27	Westchester Drive Bridge - R-SH2 Rockface between Te Marua & Birchville Park R-SH2 Featherston SuperValue Area Flooding Study/Investigation	Rockfall Flooding	LCLR	Approved
2024/27 Top of	Westchester Drive Bridge - R-SH2 Rockface between Te Marua & Birchville Park R-SH2 Featherston SuperValue Area	Rockfall	LCLR Small-to-	
2024/27	Westchester Drive Bridge - R-SH2 Rockface between Te Marua & Birchville Park R-SH2 Featherston SuperValue Area Flooding Study/Investigation SH60 Birds Hill Overslip	Rockfall Flooding Overslip	LCLR Small-to- medium	Approved Started
2024/27 Top of	Westchester Drive Bridge - R-SH2 Rockface between Te Marua & Birchville Park R-SH2 Featherston SuperValue Area Flooding Study/Investigation	Rockfall Flooding	LCLR Small-to- medium Small-to-	Approved
2024/27 Top of	Westchester Drive Bridge - R-SH2 Rockface between Te Marua & Birchville Park R-SH2 Featherston SuperValue Area Flooding Study/Investigation SH60 Birds Hill Overslip Salt Lake - Investigation only	Rockfall Flooding Overslip Flooding	LCLR Small-to- medium Small-to- medium	Approved Started Approved
2024/27 Top of	Westchester Drive Bridge - R-SH2 Rockface between Te Marua & Birchville Park R-SH2 Featherston SuperValue Area Flooding Study/Investigation SH60 Birds Hill Overslip	Rockfall Flooding Overslip	LCLR Small-to- medium Small-to-	Approved Started

	SH63 Windy Point and Narrows Rockfall	Rockfall	LCLR	Started
	SH65 Higgins Rockfall	Rockfall	LCLR	Started
	Weld Pass long term detour route	Various	Small-to-	Approved
	improvements study		medium	
	SH1 Delegat Flooding at Dashwood	Flooding	LCLR	Started
	SH63 The Wash Flooding	Flooding	LCLR	Started
	SH1 at Picton Elevation Underslip	Underslip	LCLR	Started
	SH6 Rai Saddle - Drainage and minor underslips	Underslip	LCLR	Started
	SH6 Canvastown Flooding at Racecourse Bridge	Flooding	LCLR	Started
	SH6 Kawatiri to Owen River Erosion	River erosion	LCLR	Started
New	SH1 Weld Pass underslips incl local road	Underslip	Small-to-	Approved
Projects	detour enhancement	•	medium	11
2024/27	SH63 Renwick Flooding	Flooding	LCLR	Approved
	Fairhall Diversion Flooding	Flooding	LCLR	Approved
	SH6 O'Sullivan's to Dellow's Bluff Rockfall	Rockfall	Small-to-	Approved
			medium	, .pp. 0.00
	SH6 Hope Saddle Underslip	Underslip	LCLR	Approved
	SH6 Whangamoa Hill and Rai Saddle -	Underslip	Small-to-	Approved
	Drainage and minor underslips	Oridoronp	medium	прріоточ
West Coast	SH6 Gates of Haast River Erosion	River erosion	Small-to-	Started
11001 00001	one dates of made three Eresien	111701 01001011	medium	Ciarioa
	SH6 Wanganui River Protection	River erosion	LCLR	Started
	SH6 Whataroa River Protection	River erosion	LCLR	Started
	SH73 Rock Shelter DSA and	Overslip	LCLR	Started
	Strengthening	Overenp	LOLIK	Otariou
	SH73 Otira River Bridge Abutment	Bridge scour	LCLR	Completed (Another
	Protection	2age 200a.		Funding Method)
	SH6 Buller Gorge Rock Scaling	Rockfall	LCLR	Started
	SH6 Douglas Culvert No.2 Replacement	Flooding	LCLR	Started
	Cascade Corner	Rockfall	LCLR	Started
	Cobden Hill West	Rockfall	LCLR	Started
	Depot Creek	Rockfall	LCLR	Started
	Ormon Falls	Rockfall	LCLR	Started
	East of McGraths Corner	Rockfall	LCLR	Started
	McGraths Corner	Rockfall	LCLR	Started
	Whites Bridge West Approach	Rockfall	LCLR	Started
	Rocky Point	Rockfall	LCLR	Started
	SH73 Candys Bend Scouring	River erosion	Small-to-	Started
	Cririo Canayo Dona Cocannig	11101 01001011	medium	Clariou
	SH6 Meybille Bay Slip	Overslip	Small-to- medium	Started
	SH6 Epitaph Slip - Remote Monitoring	Underslip	LCLR	Started
	SH73 Kellys Creek Bridge Replacement	Bridge Replacement	Small-to- medium	Started
New Projects 2024/27	Bens Creek Bridge	Rockfall	Small-to- medium	Approved
	Omoeroa Saddle Debris Slide	Rockfall	LCLR	Approved
	SH6 Littleman Creek - River Spurs	River Erosion	LCLR	Approved
	SH73 Kellys Creek Bridge	Business	LCLR	Approved
	Oldo bear making himself Old	Case	1.01.5	A
	SH6 Inangahua Junction Slip	Overslip	LCLR	Approved
0	SH6 Blackwater Point Dropout	Underslip	LCLR	Approved
Canterbury	Gln wye Scour	River erosion	LCLR	Completed
	Porters Pass (C)	Rockfall	LCLR	Completed
	Porters Pass (D)	Rockfall	LCLR	Completed
	West of Paddys (C)	Rockfall	LCLR	Completed

	South of Māori Creek	Rockfall	LCLR	Started
	South of T12 (Formerly SR20)	Rockfall	LCLR	Completed
	North of Wairere Stream T10 to T11	Rockfall	LCLR	Completed
	(Formerly SR27a1)			·
	Bankside flooding	Flooding	Small-to- medium	Cancelled
	Greta Valley Erosion	River erosion	LCLR	Completed
	Roidons Culvert Underslip	Underslip	LCLR	Completed
	SH8 Aires Culverts upgrades	Flooding	LCLR	Started
	SH77 Rakaia Gorge Rock fence extension and slip	Rockfall	LCLR	Started
	SH1 South Hook/Molloys/St Andrews box culvert replacements	Flooding	LCLR	Started
New	Craigeburn Cutting Underslip	Underslip	LCLR	Approved
Projects	Siberia D LHS	Rockfall	LCLR	Approved
2024/27	Siberia C LHS	Rockfall	LCLR	Approved
	Onawe Peninsula Scour	River Erosion	LCLR	Approved
	Porters culvert Aggredation	Flooding	LCLR	Approved
	SH1 Hinds Passing Lane Culvert	Flooding	LCLR	Approved
	SH79, Woodbury Road Flooding	Flooding	LCLR	Approved
	SH82 Ikawai Area Culverts to mitigate flooding	Flooding	LCLR	Approved
	SH82 Station Peak Culvert upgrade	Flooding	LCLR	Approved
	SH77 Reynolds Road and Pole Road Flooding Works	Flooding	LCLR	Approved
	Stream Training SH79 & SH1	Flooding	LCLR	Approved
	Sh77 Mt Hutt Station to Blackfords Culverts	Flooding	LCLR	Approved
Otago	SH94 Shooting Rail (Milford Road)	Underslip	LCLR	Approved
	SH8 Ash McGregors	Underslip	LCLR	Started
	SH6 Scrubby Corner	Underslip	LCLR	Started
	SH6 Nevis monitoring and maintenance plan	Rockfall	LCLR	Started
	SH8 Cromwell Gorge Slopes and Benches	Rockfall	LCLR	Started
	Coastal Otago Rock Scaling Programme	Rockfall	LCLR	Completed
New Projects	SH6 Lakeside subsidence sites SH6 (Wanaka Wakatipu)	Underslip	LCLR	Approved
2024/27	SH1 Waikouaiti Flood Mitigation	Flooding	LCLR	Approved
	SH83 Pukeuri to Duntroon Flooding	Flooding	LCLR	Approved
	SH1 Rockfall	Rockfall	Small-to-	Approved
			medium	
	SH6 Lake Wakatipu Mass Block Wall	Underslip	LCLR	Approved
Southland	SH1 Ocean Beach, Bluff	Coastal inundation / sea level rise	Small-to- medium	Started
New	SH99 McCracken's Rest Culvert		LCLR	Started
Projects 2024/27	SH99 Rileys Slip		LCLR	Started

^{*}Low-Cost Low Risk (LCLR): small projects typically under \$2 million

^{*}Small-to-medium: more complex projects over \$2 million