

# PRODUCT SAFETY RECALL

## TRAILPRO TRAILERS

**Models: Trailpro 8x4 Tradesman – Model no. TP5,  
Trailpro 8x5 Tandem – Model no. TP8.**

Sold at Bunnings stores nationwide from 1st January 2006 – 12th October 2018



### **Defect**

The trailer's drawbar may break at the front attachment bolts to the chassis, leading to failure and detachment of the drawbar. Heavy or frequent commercial use may accelerate this hazard.

### **Hazard**

Detachment of the drawbar poses significant safety hazards to other road users and bystanders.

### **What to do**

Check the identification plate on the side of the trailer's drawbar (as shown in the photo) to confirm the model number. If it's an affected model, **stop using the trailer** in a loaded capacity immediately.

### **Contact details**

If you have one of these trailers, or are in doubt, please contact Bunnings customer service centre on 0800 561 109. For more information, please go to [www.bunnings.co.nz/returns/recalls](http://www.bunnings.co.nz/returns/recalls)

Please note that NZTA-appointed inspectors have been instructed to not issue WoFs on affected models until the repair is completed.

**See [www.recalls.govt.nz](http://www.recalls.govt.nz) for  
other New Zealand consumer product recalls**

BUNZ19218